

CS/CT120007142/Riff3

ASSIGNMENT

28 Mar 2011

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBF 2471E

at Workshop m/s HUA CHIN (2000) TRADING

of 50, BUKIT BARUK ST 23

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 24716 Yr Regn: 1

Type: M/Car / M/Cycle Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____ c.c. 135

Colour RED A/C: Insured / Std / NI / NA

Sp. Reading 79280 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5YP012761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 70/90-17

R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 23/06/2020 D.O.I. 09/07/2020

Survey held at Huachan

Des. of Damages: Frt / Rear / OTS / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: 4

1)

Date/Time, File Return to?

□: Final Report

Resurvey No. of Trip:

2)

Add Fee: : Site Insp (\$

Survey Fee:

Rep-Format :

LEWIS STERN / L.E.H. (P)

☐ : Site Insp (\$

☐ : Interview (\$

Tech. Invs (\$

Violations (5

Transportation:

Transportation:

3) Photos

1. Others

TOTAL