

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/06/2020 11:38
Date Of Accident	26/06/2020 15:25
Exact Location Of Accident	SATS CARGO CENTRE (FREIGHTER BAY CHECKPOINT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	RU6857G
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	2XXXXX882K
Email Address	JEREMYC_QUEK@CERTISSECURITY.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68428849

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.5 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	MUHAMAD FADLI BIN MUHAMAD
NRIC No	SXXXX246I
Date Of Birth	25/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	01/08/2001
Driving Experience	18 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82601004
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 602A PUNGGOL CENTRAL #04-680
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : STAFF GENDER: : MALE
Passenger 2	NAME: : STAFF GENDER: : MALE
Passenger 3	NAME: : STAFF GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO INCIDENT REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WD1036Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. The report correctly details the details of this accident to speed up the claims process
2. The form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insureds constitutes not an admission of policy liability on the part of the insureds or companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore (GISAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to top up of the report being made available afterwards.
8. Consent under the Personal Data Protection Act (PDPA)

³ understand, acknowledge, agree and consent that.

- My Insurer, my Workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicle(s) involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to the third party service providers or agents/including their lawyers/law firms, which may be located outside of Singapore for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile a claim's history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any legal actions, laws or court orders.




Polymers det. 1
Date & Time

Driver's Signature _____
 (If driver is not the policyholder)
 Date & Time 26/6/2020 15:50:31

Reporting Center Personnel's Signature
Name Quack Knott
NHTC ID No. 2

7960



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As the date 26 JUNE 2020 time 1525hrs vehicle RU68574 was hit rear end during stationary waiting to exit the cargo freighter bay checkpoint by SATIS tractor driver WD10364 MR NH CHAN LEE was the tractor driver.

- The back rear end bumper RU68574 was damaged.
- No visible damage to tractor WD10364
- No injury to report.
- Rear end bumper back door damaged.
- Vehicle RU68574 was stationary waiting to exit
- checkpoint at the time the accident occurred.
- Cargo SATIS freighter bay 4S10.

DECLARATION

I, We declare the above particulars are true in every respect.



Printed Name: [Signature]

Date & Time: 26/6/2020/1525hrs

Driver's Signature: [Signature]

Date & Time: 26/6/2020/1525hrs

Reps SATIS Centre Employee Signature: [Signature]

Name: [Signature]

NRCCS No: [Signature]