

10-10-68

Veh No: 6BF3617X Yr Regn: 2016 / Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick Up

Make: White Mt Lugo 2742

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 97186 T/Radio: Insured / Std / NI / NA

Eng/No: _____

CIN: MMAJYKLI0G17024/36

Gen. Cond. Good) Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

N/S	O/S

Tyre Size: F: 245/70R16

R: 245/70R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO of D ~~Japan~~

Front Rear

R/Bal. 86 mm R/Bal. 86 mm

L/Bal. $\frac{15}{06}$ mm L/Bal. $\frac{15}{06}$ mm

D.O.A. _____ D.O.I. 24/07/20

Survey held at Dynamk.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Prel. Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

□: Interview (9)

Tech. Inve. G.

West 45

Transportation:

1. Fluids

A. 1000000

TEST 3)