Surveyor:

REF: CS3/AIG20004437/Bqf3-1

Special Instruction:

LS $20,750.00

Third Parties:

Claimant: Owner

Surveyor: Auto Performance

Workshop: Sze Kang Automobile

ASSIGNMENT (Office)

From (Person): Lee Ming Yao of AIG Date/Time: 09/07/2020

Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: ET 9292A Insured: SLR 5601X

at Workshop m/s _____ Tel: _____

of 11 Yishun Industrial St 1, #01 – 103 Northspring Bizhub, Singapore 768089

Policy No: 1700050249 Claim No: 2475511340SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/03/2020

(Client's Record)

16 July 2020 10am - 5pm

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, ___days (Red $____/___%; Original 05 days)

Date/Time: 28/07/20 Submit ~~Final Fig~~ LS $10900, 4 days (Red $ 9850 / 47 %; Original 5 days)

Date/Time	Action/Instruction
	ET 9292A - X
	SLR 5601X - X

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/ Evaluated by:

Fee Charged:	Date:
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time 28/07/20 File Pass to Typist 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____