



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20004437/Bqf3s2-1

78 SHENTON WAY #09-16  
AIG BUILDING  
SINGAPORE 079120

Date : 29-07-2020



ATTN: LEE MING YAO

Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	SLR 5601X	<b>Veh. Inspected</b>	ET 9292A
<b>Policy No.</b>	1700050249	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	2475511340SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LEE MING YAO	<b>Assign Date</b>	09/07/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN GTR 3.8 (A)	<b>c.c</b>	3799
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	R35005299	<b>Colour</b>	GREY
<b>Odometer</b>	110542	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	285/35 ZR20	MICHELIN	6 mm
<b>L/H Front Tyre</b>	285/35 ZR20	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	305/30 ZR20	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	305/30 ZR20	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/03/2020	<b>Inspection Date</b>	16/07/2020
<b>Survey held at</b>	11 Yishun Industrial St 1 #01-103 Singapore 768089		
<b>Repairer</b>	SZE KANG AUTOMOBILE SPRAYING SERVICES		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**