

MCS Garage

TP.111
Denise.

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

WDD2120342B314539

Vehicle number: SLN8000G

Vehicle Made & Model: MERCEDES-BENZ E200

Qty	List Items	Amount \$
1	Front bumper <i>Deformed</i>	1,843.14 ✓ 1435
1	Front bumper side grille <i>Not new</i>	94.12 ✗
2	Front bumper PDC sensors - RH @ 282.33 <i>1 piece damaged</i>	564.66 282.33
1	Front bumper lower moulding - RH <i>Not new</i>	176.11 ✗
1	Front bumper sponge <i>Deformed</i>	182.42 ✗
1	Front bumper reinforcement <i>Not new</i>	769.82 ✗
1	Front bumper side bracket - RH <i>New</i>	115.20 68
1	Front fender - RH <i>Buckled</i>	1,198.78 ✓ 1139
1	Front fender inner shield <i>Deformed</i>	128.53 ✓
1	Front headlamp - RH <i>Not</i>	3,397.46 ✓
1	Front headlamp bracket - RH <i>Not new</i>	142.50 ✗
1	Front shock absorber - RH <i>Not new</i>	680.50 ✗
1	Front top arm	6450.32 ✗
1	Front lower arm	5805.28 ✗
1	Front knuckle arm	560.20 ✗
1	Front wheel bearing	588.60 ✗
		1,265.50 ✗
		681.50 ✗
Sub-total		12,389.04
Less 10%		1,238.90
Total List		11,150.14

Special Nett Items		
1	Front sport wheel - RH <i>Not</i>	1,500.00 750
1	Front tyre - RH <i>Not new</i>	800.00 ✗
Total Special Nett		2,300.00

Vehicle number: SLN8000G

Vehicle Made & Model: MERCEDES-BENZ E200

Labour charges

To check front electrical wiring
To remove, refix front undercarriage
To check wheel alignment
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

1010

50.00	30
250.00	X
120.00	80
80.00	X
1,200.00	500
1,200.00	400.
Total Labour	2,900.00

total: 7565.28.

4/s. 6K.

04 Days.

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

16,350.14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: