



## Service Request Details

Claim	SOM02GLO
Reference	CS3/ASM20002766/Qqf3e2-1 
Loss Date	17 January 2020
Report Date	18 Feb 2020 9:22:18 AM
Request Date	9 July 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Re-inspection

### Actions

Next Step      Wait for: Approve invoice

Add Invoice

### Vehicle Information

Incident Vehicle      YN7916S  
Registration #

Make      TPVD ISUZU

Model      NPR75UH5A

### Service Address

No.2 ANG MO KIO STREET 63, , , 569111

### Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD  
No.2 ANG MO KIO STREET 63, 569111, Singapore

### Claim Handler

TAN Wancong

Additional Instructions

please do physiscal Reinspection

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 <a href="#">ASM-LKKInvoice-AC2005319.pdf</a>	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2020
 <a href="#">LKKInspection.pdf</a>	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2020
 <a href="#">LKKAdjustment.pdf</a>	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2020
 <a href="#">LKK photo.pdf</a>	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2020
 <a href="#">RI Details.msg</a>	Letters and Correspondence	Solicitor / Advocate	TAN Wancong	9 July 2020
 <a href="#">Survey report with color photos.tif</a>	Letters and Correspondence	Solicitor / Advocate	TAN Wancong	23 April 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP LIT LOD.msg	Legal	Letter of Demand/Notice of Proceedings	TAN Wancong	23 April 2020
 YN7916S TP GIA.PDF	Forms / Claim Documents	Claim Form	NIKAM Santosh Pandurang	18 February 2020
 SHD9989Y INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	18 February 2020