

ASS. REC. BY:

Sua Pa

REF:

NT4C

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHE 1027R

Yr Regn:

17/12/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1746

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

500764

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364405754608

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

P: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / VOKO or \$

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

07/07/2020

D.O.I.

08/07/2020

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                               |
|-------------|----------------------------------------------------|
|             | TP.                                                |
|             | TAX/07/20/2011                                     |
|             | STM 9694 B                                         |
|             | L/S \$3300.00 REPAIR 5 DAYS (RED: \$14000.00, 80%) |

Date/Time, File Pass to?



Prell. Report

1)



Final Report

Date/Time, File Return to?

2) 18/08/20 TYPIST

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Phone

Others

TOTAL

Report Form:

Lump Sum / L.B.I. / L/S \$3300.00

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                                      |
| Owner ID Type:                                                                                                                                                                                                          | Company                              |
| Owner ID:                                                                                                                                                                                                               | 369K                                 |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                                      |
| Vehicle No.:                                                                                                                                                                                                            | SHF1027R                             |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                                   |
| Intended Deregistration Date:                                                                                                                                                                                           | 09 Jul 2020                          |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                               |
| Vehicle Model:                                                                                                                                                                                                          | PRIUS TAXI (SMRT)                    |
| Primary Colour:                                                                                                                                                                                                         | Maroon                               |
| Manufacturing Year:                                                                                                                                                                                                     | 2014                                 |
| Engine No.:                                                                                                                                                                                                             | 2ZR6243272                           |
| Chassis No.:                                                                                                                                                                                                            | JTDKN36U405754608                    |
| Maximum Power Output:                                                                                                                                                                                                   | 100.0 kW (134 bhp)                   |
| Open Market Value:                                                                                                                                                                                                      | \$32,920.00                          |
| Original Registration Date:                                                                                                                                                                                             | 17 Dec 2014                          |
| First Registration Date:                                                                                                                                                                                                | 17 Dec 2014                          |
| Transfer Count:                                                                                                                                                                                                         | 0                                    |
| Actual ARF Paid:                                                                                                                                                                                                        | \$8,088.00                           |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                                      |
| PARF Eligibility:                                                                                                                                                                                                       | Yes                                  |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | 16 Dec 2022                          |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$5,661.00                           |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                                      |
| COE Expiry Date:                                                                                                                                                                                                        | 16 Dec 2022                          |
| COE Category:                                                                                                                                                                                                           | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                                                                                                                                                                                                      | 8                                    |
| PQP Paid:                                                                                                                                                                                                               | \$51,668.00                          |
| COE Rebate Amount:                                                                                                                                                                                                      | \$15,729.00                          |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$21,390.00</b>                   |
| <b>Message</b>                                                                                                                                                                                                          |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 09 Jul 2020

OK

(L/c/c)

MSR120057553 / SMRT Automotive Services Pte Ltd - Woodlands  
 ENTRY DATE & TIME 07/07/2020 13:34  
 SUBMITTED BY: B. Thairai Nayagi

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                         |
|----------------------------|-----------------------------------------|
| Date Of Report             | 07/07/2020 13:34                        |
| Date Of Accident           | 07/07/2020 12:25                        |
| Exact Location Of Accident | SLIP ROAD FROM PIE TOWARDS TOH GUAN AVE |
| Country/State of Loss      | SINGAPORE                               |

### DETAILS OF OWN VEHICLE

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | SHF1027R           |
| <b>Insured/Policyholder</b> |                    |
| Name Of Registered Owner    | SMRT TAXIS PTE LTD |
| Co Reg No                   | 1XXXXX369K         |
| Email Address               | NOEMAIL            |
| Mobile Phone No             |                    |
| Alternative Phone No        | OFFICE-80000000    |

### Vehicle Particulars

|                                                                              |                    |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer                                                                 | TOYOTA             |
| Model                                                                        | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | HIRE AND REWARD    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category                                                             | TAXI               |

### Insurance Company

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage          | THIRD PARTY                    |
| Fleet Policy              | YES                            |
| Policy Number             | D-20095484MFSH                 |
| Cover Note Number         |                                |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | TAN WUI TAT           |
| NRIC No              | SXXXX984G             |
| Date Of Birth        | 12/07/1961            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 03/12/1982            |
| Driving Experience   | 37 YEARS AND 7 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-80000000  |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | NOEMAIL               |

|                                                     |               |
|-----------------------------------------------------|---------------|
| Address                                             | 11            |
| Postcode                                            |               |
| Was driver an employee of the Insured's Company     | NO            |
| If No, Relationship of the Driver with the Insured  | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | -             |
|                                                     | -             |
| Insurance Company of Driver's Own Vehicle           | -             |
|                                                     | -             |
|                                                     | -             |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM PIE TOWARDS TOH GUAN AVENUE AS I WAS LOOKING OUT AT THE ON COMING TRAFFIC. WHILST I WAS STATIONARY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJM9694B HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### Attachment(s)

|                                               |              |
|-----------------------------------------------|--------------|
| Are accident photos available for attachment? | YES          |
| Was there any video captured by Car Camera?   | YES          |
| Remarks/ Reasons:                             | FILE TOO BIG |
| Was there any audio recorded?                 | NO           |


#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                           |
|-------------------------------------|---------------------------|
| Vehicle Registration Number         | SJM9694B                  |
| Vehicle Make/Model/Colour           |                           |
| Details Of Properties               |                           |
| Vehicle Category                    | PRIVATE CAR               |
| Name of Driver                      | TAN BO RONG (CHEN BORONG) |
| NRIC/Passport Number                | SXXXX152G                 |
| Contact Number                      |                           |
| Address                             |                           |
| Postcode                            |                           |
| Insurance Company Name              |                           |
| Nature Of Damage                    |                           |
| No. Of Passenger (Including Driver) |                           |

### Sketch Plan Pg. 1

### SKETCH PLAN

Slip Rd from PIE Toh Guan Ave



A- SHF1027R

B - SJM9694B

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 7/1/2020

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Case Details

Case Reference Number :

TAX/07/20/2011

Type of Repair : Accident Repair

Vehicle Registration Number :

SHF1027R

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-11997-ID

Assigned By : Taxi Claims Manager  
TeamInsurance Company Name : NTUC Income Insurance Co-operative  
Ltd

Accident Date and Time : 07/07/2020 04:25 AM

Vehicle Age(In Months) : 67

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation |              |         |                 |                                |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|---------------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | BUMPER REAR                    | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace           | 1                 | 343.95                   | Replace        | ✓ / CRU |
| One Time Key In     | Main         |         |                 | BUMPER CLIPS                   | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace           | 10                | 12.08                    | Replace        | ✓ / NEC |
| One Time Key In     | Main         |         |                 | BUMPER REINFORCEMENT REAR      | 1   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace           | 0                 | 0                        | Check          | ✓ X SRC |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, RR BUMPER LH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 0                 | 0                        | Check          | ✓ X SRC |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, RR BUMPER RH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 0                 | 0                        | Check          | ✓ X SRC |
| One Time Key In     | Main         |         |                 | ANTENNA, ELECTRICAL LOWER REAR | 1   | 157.40                  | 157.40         | 10.00  | 141.66          | Replace           | 0                 | 0                        | Check          | ✓ X SRC |
| One Time Key In     | Main         |         |                 | SENSOR REVERSE                 | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace           | 1                 | 180.00                   | Replace        | ✓ short |
| One Time Key In     | Main         |         |                 | PIXEL STICKER                  | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace           | 2                 | 120.00                   | Replace        | ✓ / NEC |
| One Time Key In     | Main         |         |                 | BUMPER LIP COVER RR/LH         | 1   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace           | 0                 | 0                        | Not Give       | ✓ X SRC |

Total Spare Part Cost 13,602.13

Surveyor Total 1,435.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,881.70

Final Sur Total 1,148.22

| SMRT Recommendation |              |         |                 |                               |     |                         |                |        |                 |                | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | BUMPER LIP COVER RR/RH        | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | BUMPER LIP REAR               | 1   | 228.90                  | 228.90         | 25.00  | 171.68          | Replace        | 0                 | 0                        | Check          | ✓ XSV   |
| One Time Key In     | Main         |         |                 | BUMPER SEAL, RR LH            | 1   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | BUMPER SEAL, RR RH            | 1   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | BUMPER SIDE RETAINER RR/LH    | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace        | 1                 | 71.10                    | Replace        | ✓ /BR   |
| One Time Key In     | Main         |         |                 | BUMPER SIDE RETAINER RR/RH    | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace        | 1                 | 71.10                    | Replace        | ✓ /BR   |
| One Time Key In     | Main         |         |                 | UNDER COVER SUBASSY, RR FLOOR | 1   | 514.50                  | 514.50         | 25.00  | 385.88          | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | EXHAUST HEAT SHIELD, REAR     | 1   | 107.40                  | 107.40         | 25.00  | 80.55           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | EXHAUST TAIL PIPE             | 1   | 656.20                  | 656.20         | 25.00  | 492.15          | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | SUPPORT, EXHAUST REAR         | 2   | 33.60                   | 67.20          | 25.00  | 50.40           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | NAME PLATE (HYBRID)           | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace        | 1                 | 38.92                    | Replace        | ✓ /Nec  |
| One Time Key In     | Main         |         |                 | NAME PLATE (PRIUS)            | 1   | 60.80                   | 60.80          | 25.00  | 45.60           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | NAME PLATE (TOYOTA)           | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | SPOILER REAR                  | 1   | 953.70                  | 953.70         | 25.00  | 715.28          | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |
| One Time Key In     | Main         |         |                 | 3RD BRAKE LAMP                | 1   | 231.30                  | 231.30         | 25.00  | 173.48          | Replace        | 0                 | 0                        | Not Give       | ✓ XSV   |

Total Spare Part Cost 13,602.13

Surveyor Total 1,435.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,881.70

Final Sur Total 1,148.22

| SMRT Recommendation |              |         |                 |                                 |     |                         |                |        |                 | Surveyor Approval |                   |                          |                        |
|---------------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|------------------------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace Remarks |
| One Time Key In     | Main         |         |                 | SMRT LOGO                       | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | STICKER DECAL 6555 8888         | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | END PANEL                       | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace           | 0                 | 0                        | Check ✓ X sue          |
| One Time Key In     | Main         |         |                 | END PANEL COVER, DECK TRIM HOLE | 1   | 46.10                   | 46.10          | 25.00  | 34.58           | Replace           | 0                 | 0                        | Check ✓ X sue          |
| One Time Key In     | Main         |         |                 | END PANEL COVER, DECK TRIM, RR  | 1   | 121.10                  | 121.10         | 25.00  | 90.82           | Replace           | 0                 | 0                        | Check ✓ X sue          |
| One Time Key In     | Main         |         |                 | REINFORCEMENT, RR               | 2   | 34.60                   | 69.20          | 25.00  | 51.90           | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | SEALANT SIKAFLEX                | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | SPARE TYRE PANEL                | 1   | 667.70                  | 667.70         | 25.00  | 500.78          | Replace           | 0                 | 0                        | Check ✓ X sue          |
| One Time Key In     | Main         |         |                 | MEMBER SUB-ASSY, RR LH          | 1   | 174.10                  | 174.10         | 25.00  | 130.57          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | MEMBER SUB-ASSY, RR RH          | 1   | 174.10                  | 174.10         | 25.00  | 130.57          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | FLOOR PANEL RR/RH               | 1   | 209.90                  | 209.90         | 25.00  | 157.43          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | BOX, DECK FLOOR, RR             | 1   | 649.70                  | 649.70         | 25.00  | 487.28          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | BOX, RR FLOOR, BOARD            | 1   | 679.60                  | 679.60         | 25.00  | 509.70          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | BOARD, RR FLOOR                 | 1   | 392.30                  | 392.30         | 25.00  | 294.23          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |
| One Time Key In     | Main         |         |                 | BOARD ASSY, RR RH               | 1   | 379.20                  | 379.20         | 25.00  | 284.40          | Replace           | 0                 | 0                        | Not Give ✓ X sue       |

Total Spare Part Cost 13,602.13

Surveyor Total 1,435.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,881.70

Final Sur Total 1,148.22

| SMRT Recommendation |              |         |                 |                       |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-----------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | SPACER, RR FLOOR      | 1   | 130.60                  | 130.60         | 25.00  | 97.95           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | CUSHION, SPARE WHEEL  | 1   | 230.80                  | 230.80         | 25.00  | 173.10          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | PROTECTOR, SPARE      | 1   | 143.70                  | 143.70         | 25.00  | 107.77          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | CARRIER, SPARE        | 1   | 19.70                   | 19.70          | 25.00  | 14.77           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | TYRE                  | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | WHEEL, DISC           | 1   | 1,490.20                | 1,490.20       | 25.00  | 1,117.65        | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | PANEL ASSY, DECK RH   | 1   | 307.00                  | 307.00         | 25.00  | 230.25          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | BATTERY               | 1   | 278.00                  | 278.00         | 10.00  | 250.20          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | BATTERY CLAMP         | 1   | 16.10                   | 16.10          | 25.00  | 12.08           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | BATTERY TRAY          | 1   | 42.80                   | 42.80          | 25.00  | 32.10           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | TAIL LAMP BRACKET, LH | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace         | 0                 | 0                        | Check          | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | TAIL LAMP LH          | 1   | 548.40                  | 548.40         | 10.00  | 493.56          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | FENDER LINER RR/LH    | 1   | 141.30                  | 141.30         | 25.00  | 105.98          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | TAIL LAMP BRACKET, RH | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace         | 0                 | 0                        | Check          | ✓ Xsrc  |
| One Time Key In     | Main         |         |                 | TAIL LAMP RH          | 1   | 557.80                  | 557.80         | 10.00  | 502.02          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsrc  |

Total Spare Part Cost 13,602.13

Surveyor Total 1,435.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,881.70

Final Sur Total 1,148.22

| SMRT Recommendation |              |         |                 |                                        |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|----------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                              | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | TROUGH, BACK DOOR                      | 1   | 110.90                  | 110.90         | 25.00  | 83.18           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | FENDER RR/RH                           | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | SMRT LOGO                              | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | STICKER DECAL 6555 8888                | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | FENDER LINER RR/RH                     | 1   | 141.30                  | 141.30         | 25.00  | 105.98          | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | TAILGATE ASY                           | 1   | 1,007.90                | 1,007.90       | 25.00  | 755.92          | Replace         | 1                 | 0                        | Repair         | ✓ X R   |
| One Time Key In     | Main         |         |                 | DAM, BACK DOOR GLASS ADHESIVE, NO.1    | 1   | 27.30                   | 27.30          | 25.00  | 20.48           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, LH      | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, RH      | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | MOULDING BACK WINDOW, LOWER NO.1       | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | DAM, BACK DOOR GLASS ADHESIVE, NO.2    | 1   | 17.40                   | 17.40          | 25.00  | 13.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, LOWER NO.2      | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, OUTSIDE LH NO.2 | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, OUTSIDE RH NO.2 | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |
| One Time Key In     | Main         |         |                 | SEALANT W/SCREEN                       | 3   | 37.00                   | 111.00         | 0.00   | 111.00          | Replace         | 0                 | 0                        | Not Give       | ✓ X Svc |

Total Spare Part Cost 13,602.13

Surveyor Total 1,435.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,881.70

Final Sur Total 1,148.22

| SMRT Recommendation   |              |         |                 |                             |     |                         |                |        |                 |                          | Surveyor Approval |                          |                        |
|-----------------------|--------------|---------|-----------------|-----------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|------------------------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace Remarks |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR HINGE LH/RH   | 2   | 58.30                   | 116.80         | 25.00  | 87.45           | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR LOCK          | 1   | 444.10                  | 444.10         | 25.00  | 333.08          | Replace                  | 1                 | 333.08                   | Replace ✓ Jym          |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR STAY LH       | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR STAY RH       | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR WEATHER STRIP | 1   | 353.40                  | 353.40         | 25.00  | 265.05          | Replace                  | 1                 | 265.05                   | Replace ✓ CRU          |
| One Time Key In       | Main         |         |                 | TAILGATE LOCK, COVER        | 1   | 15.70                   | 15.70          | 25.00  | 11.77           | Replace                  | 0                 | 0                        | Check ✓ XSV            |
| One Time Key In       | Main         |         |                 | TAILGATE OUTSIDE GARNISH    | 1   | 504.90                  | 504.90         | 25.00  | 378.67          | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| One Time Key In       | Main         |         |                 | STRIKER, BACK DOOR          | 1   | 48.90                   | 48.90          | 25.00  | 36.67           | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| One Time Key In       | Main         |         |                 | EMBLEM REAR                 | 1   | 60.30                   | 60.30          | 25.00  | 45.22           | Replace                  | 0                 | 0                        | Not Give ✓ XSV         |
| Total Spare Part Cost |              |         |                 |                             |     |                         |                |        | 13,602.13       | Surveyor Total 1,435.28  |                   |                          |                        |
| Lump Sum Discount (%) |              |         |                 |                             |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                        |
| Final Spare Part Cost |              |         |                 |                             |     |                         |                |        | 10,881.70       | Final Sur Total 1,148.22 |                   |                          |                        |

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 1,352.00                | 400                     | ✓       |
| Total: |              |                        | 1,352.00                | 400.00                  |         |

Spray Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER | 378.00                  | 200                     | ✓       |
| 2      | Main         | TO RESPRAY BUMPER BEAM | 180.00                  | 0                       |         |
| Total: |              |                        | 3,114.00                | 400.00                  |         |

| S.No.         | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 3             | Main         | TO RESPRAY TAIL GATE                | 378.00                  | 200                     |         |
| 4             | Main         | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00                  | 0                       |         |
| 5             | Main         | TO RESPRAY REAR SPOILER             | 180.00                  | 0                       |         |
| 6             | Main         | TO RESPRAY REAR PANEL               | 180.00                  | 0                       |         |
| 7             | Main         | TO RESPRAY REAR SPARE TYRE PANEL    | 180.00                  | 0                       |         |
| 8             | Main         | TO RESPRAY RIM                      | 180.00                  | 0                       |         |
| 9             | Main         | TO RESPRAY REAR MEMBER,RH           | 180.00                  | 0                       |         |
| 10            | Main         | TO RESPRAY REAR MEMBER,LH           | 180.00                  | 0                       |         |
| 11            | Main         | TO RESPRAY REAR FLOOR SIDE PANEL RH | 180.00                  | 0                       |         |
| 12            | Main         | TO RESPRAY TROUGH BACK DOOR RH      | 180.00                  | 0                       |         |
| 13            | Main         | TO RESPRAY REAR FENDER RH           | 378.00                  | 0                       |         |
| 14            | Main         | TO RESPRAY BATTERY PANEL            | 180.00                  | 0                       |         |
| <b>Total:</b> |              |                                     | <b>3,114.00</b>         | <b>400.00</b>           |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                                                            | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|----------------------------------------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION                                  | 80.00                   | 20                      |         |
| 2             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                              | 200.00                  | 30                      |         |
| 3             | Main         | TO DO WHEEL ALIGNMENT / TYRE BALANCING                               | 120.00                  | 0                       |         |
| 4             | Main         | TO ALIGN CHASSIS                                                     | 350.00                  | 0                       |         |
| 5             | Main         | TO REMOVE & REFIT EXHAUST                                            | 120.00                  | 0                       |         |
| 6             | Main         | TO TRANSFER REAR TAILGATE MECHANISM                                  | 120.00                  | 0                       |         |
| 7             | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM                              | 120.00                  | 30                      |         |
| 8             | Main         | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | 120.00                  | 0                       |         |
| <b>Total:</b> |              |                                                                      | <b>1,950.00</b>         | <b>80.00</b>            |         |

| S.No.         | Costing Type | Job Scope                                                                     | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------------------------------------------------|----------------------------|----------------------------|---------|
| 9             | Main         | TO INSPECT RR LIGHTING,<br>MECHANISMS & WATER TEST RR<br>LIGHTING FOR LEAKAGE | 120.00                     | 0                          |         |
| 10            | Main         | TO REMOVE AND REFIX REAR<br>WINDSCREEN                                        | 240.00                     | 0                          |         |
| 11            | Main         | TO REMOVE AND REFIT WIRE<br>HARDESS                                           | 200.00                     | 0                          |         |
| 12            | Main         | TO REPLACE SUNDRY PARTS                                                       | 100.00                     | 0                          |         |
| 13            | Main         | TO WASH AND VACUUM                                                            | 80.00                      | 0                          |         |
| <b>Total:</b> |              |                                                                               | <b>1,950.00</b>            | <b>80.00</b>               |         |

## Summary

|                          | Estimator Assessment(\$)                                                            | Surveyor Assessment(\$)                                                               |
|--------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Total Spare Part Detail  | 10,881.70                                                                           | 1,148.22                                                                              |
| Total Labour Cost        | 1,352.00                                                                            | 400.00                                                                                |
| Total Spray Painting     | 3,114.00                                                                            | 400.00                                                                                |
| Other                    | 1,950.00                                                                            | 80.00                                                                                 |
| Overall Total            | 17,297.70                                                                           | 2,028.22                                                                              |
| Lump Sum Repair Option   | <input type="checkbox"/>                                                            | <input checked="" type="checkbox"/>                                                   |
| Lump Sum Total           | 17,300.00                                                                           | 2,050.00                                                                              |
| Surveyor Approved Amount |                                                                                     | 2,050.00                                                                              |
| No of Repair Days*       | 9                                                                                   | 3                                                                                     |
| Remarks                  |                                                                                     | L/S, after paint photo                                                                |
| Surveyor Name            |                                                                                     | Sun Pin (LKK)                                                                         |
| Signature                |  |  |

Survey Date 08/07/2020

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: