

ASS. REC. BY:

REF: CS/MSG20007226/Ksf3

Special Instruction:

Surveyor: KENNETH ASSIGNMENT (Office)From (Person): Monica Chung of MSIG Date/Time: 13 Jul 2020 15:00

Estimated Cost: _____ Bill to: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJM 4635E Insured: SLS 3908Uat Workshop m/s BIFROST Tel: 9792 1329of Blk 9 Sector C, #01-42 Sin Ming Industrial EstatePolicy No: 29095146 Claim No: 625898

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/07/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 13-7-20 3.30P.M Person Contacted: LIM Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	INSURANCE: BLK 176 SIN MING AUTOCARE #03-09
	SJM 4635E - ☒
	SLS 3908U - ☒