



PRI Header Details

Claim No	D20002730MFSH	Policy No	D-20094922MFSH	Claimant S.No & Name	1 & BIFROST
Workshop Name	BIFROST AUTO PTE LTD (Contact Person : IKHWAN)	Survey Location & Contact Details	8 KAKI BUKIT AVE 4 #01-49, PREMIER @ KAKI BUKIT Mobile: 93290237 , Phone: 0 , Fax: 0 EmailId: CLAIMS_RAR@BIFROSTAUTO.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8736Y	TP Vehicle No	SLQ3705Z
PRI Recieved Date	09-07-2020 09:21:45 PM	Surveyor Appointed Date	13-07-2020 04:31:29 PM	Surveyor Accept Date	13-07-2020

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	13-07-2020	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount	□	Surveyor Fees	□	Remarks	