

ASS. REC. BY: ForanREF: CC4/LPC20007240/

PS3

SICA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGR 686Tat Workshop m/s cycle & carriageof 188, Pansow LoopInsured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 109K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGR 686TYr Regn: 2017 / FEBType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MERCEDES BENZ C180 N/A c.c 1595Colour: BLACK

A/C: Insured / Std / NI / NA

Sp Reading: 107791

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050402R243661Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: NI / S/Rim / STD A/Rim or _____Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/07/2020D.O.I. 27/07/2020

Survey held at

cycle & carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.R. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	423D
Vehicle No.:	XE5168G
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jul 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FP70HDR2VDEA
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	470912C0470196
Chassis No.:	FP70HDA00023
Maximum Power Output:	-
Open Market Value:	\$96,707.00
Original Registration Date:	10 Sep 2019
First Registration Date:	10 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$4,836.00

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	09 Sep 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,501.00
COE Rebate Amount:	\$24,166.00
Total Rebate Amount:	\$24,166.00

The information contained herein is correct as at 27 Jul 2020

OK

art.com/used_cars/info.php?ID=896806&DL=1094

Mercedes-Benz C-Class C180 Avantgarde

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$109,800		
Depreciation ?	\$13,750 /yr View models with similar depre	Reg Date	17-Feb-2017 (6yrs 6mths 20days COE left)
Mileage	39,176 km (11.4k /yr)	Manufactured ?	2016
Road Tax ?	\$740 /yr	Transmission	Auto
Dereg Value ?	\$62,853 as of today (change)	OMV ?	\$37,206
COE ?	\$51,109	ARF ?	\$39,089
Engine Cap	1,595 cc	Power	115.0 kW (154 bhp)
Curb Weight ?	1,425 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		

Features

1.6L 4 Cylinder Inline Turbocharged Engine, 154Bhp, Paddle Shifters, ABS, ESP, 8 x SRS Airbags, Agility Select, Auto Start/Stop Function, Cruise Control. View specs of the Mercedes-Benz C-Class Saloon (2014-2018)

Accessories

17" S/Rims, Factory Audio Sound System With Bluetooth/AUX/USB, Telephony, 2 x Electric Memory Leather Seats, Park Assist, Reverse Camera, Rain Sensors.

De