

egn: 2019, April

Veh No: SHC 7767 P Yr Regn: 2019, Apr 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq C.C. 1580

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading 77208 T/Radio: Insured / Std / NI / NA

Eng/No: G4LEJU192193

C/No: KMH C851CV/KU141416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of Michelin

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 12/07/2020 D.O.I. 14/07/2020

Survey held at Sigust Sin King

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The W/C / Chassis frame / Body Structure affected due to collision

The C/S / chassis frame / Body structure checked and is complete.

Days Of Receipt

Days Of Repair: _____
Duration of Time: _____
Customer's Name: _____
Customer's Address: _____
City: _____ State: _____ Zip: _____
Phone Number: _____
E-mail Address: _____
Signature: _____
Date: _____
Printed Name: _____
Title: _____
Company: _____
Address: _____
City: _____ State: _____ Zip: _____
Phone Number: _____
Fax Number: _____
E-mail Address: _____
Signature: _____
Date: _____
Printed Name: _____
Title: _____
Company: _____
Address: _____
City: _____ State: _____ Zip: _____
Phone Number: _____
Fax Number: _____
E-mail Address: _____Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____

Fee:	Site Insp (\$	S+BS \$	SI
------	---------------	---------	----

Interview (\$	Photos
---------------	--------

	Tech. Invs (\$	Others
--	----------------	--------

Weekend (\$	
-------------	--

	TOTAL	
--	-------	--

100