

ASS. REC. BY:

REF: CS3/LPC20007278/Gtf3

Special Instruction:

Surveyor: GQASSIGNMENT (Office)From (Person): ONG LI LI of LPC Date/Time: 14/7/2020 2:11 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLW 2714Y Insured: YN 7812Hat Workshop m/s Lim Motor Pte Ltd Tel: 65527761of 160 Sin Ming Drive Sin Ming AutoCity #05-20Policy No: _____ Claim No: 20/20/20/VC05/023458

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 14-7-20 3.11P.MPerson Contacted: SAMANTHA Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLW 2714Y - ☒
	YN 7812H - CS/LPC19010948/Kqd3e2 DOA : 18/06/2019