

China - L3000

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATEDate: 11.07.2020
Time: 12:51:50
Page: 1COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755JOB NO : 305410353
REGN NO : SH 8573T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 12.05.2016
DATE/TIME IN : 10.07.2020 23:15
ACCIDENT DATE : 10.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de ✓
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	Br ✓
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	net ✓
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0006	04-01-0103-0577-G	PANEL ASSY-TRUNK LID#	1	2,174.90	20.00	1,739.92	fx ✓
0007	04-01-0103-0787-G	EMBLEM-I40	1	27.90	20.00	22.32	net ✓
0008	04-01-0103-0786-G	EMBLEM-CRDI	1	27.90	20.00	22.32	net ✓
0009	04-01-0103-0800-G	SYMBOL MARK-TRUNK LID	1	28.70	20.00	22.96	net ✓
0010	28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG	1 N	30.00	2.00-	30.00	net ✓
0011	28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL	1 N	30.00	0.20	30.00	net ✓
0012	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	0.02-	50.00	net ✓
0013	04-01-0103-0907-G	BRKT ASSY-RR BUMPER SIDE	1	35.60	20.00	28.48	de ✓

P1.0

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.07.2020
Time: 12:51:50
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305410353
REGN NO : SH 8573T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 12.05.2016
DATE/TIME IN : 10.07.2020 23:1
ACCIDENT DATE : 10.07.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS	1	N	135.70	2.00-	135.70

SUB-TOTAL : 3,604.82

JOB NATURE

0000 PB	PANEL BEATING	900.00	560
0001 SP	SPRAYPAINT CHARGE	800.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 1,830.00

TOTAL : 5,434.82

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanpin 97415144
13/7/20
Lumpsum
Resurvey after repair
3 days
tanpin @ (handwritten)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Luyang Drive Singapore 508939 24 Serangoon Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609266 501 Yishun Industrial Park A Singapore 768732
320 Yishun Road Singapore 768732

Date/Time: 11.07.2020 12:29

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305410353

OWNER

IS COMFORT TRANSPORTATION PTE LTD
OWNER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


OUNT CARD NO.

REGN NO. SH 8573T	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 10.07.2020 23:15
YR OF MANU. 12.05.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU087927	COMPLETION DATE/TIME

Accident Date: 10.07.2020
NATURE: 3P 10.07.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SH 8573T

JU CHINA LKK

Vehicle No.:

SH 8573T

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard