ASS. REC. BY: Kenneth

REF: AIG/ 20007289/Ke

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG 9524S Yr Regn: 10 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toy Agya c.c 1496

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 253134 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP106 · 531199

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: NIL S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Sunwide

Front		Rear	
R/Bal.	7 mm	R/Bal.	8 mm
L/Bal.	7 mm	L/Bal.	8 mm
D.O.A.	11/7/20	D.O.I.	15/7/2020

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FM & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) _____ ☐ : Prell. Report ☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ Tech Invs ($ _____) ☐ Weekend ($ _____)

Survey Fee: _____

Transportation: _____ $ - RS. ___ SI

Fuel: _____

Others: _____

TOTAL: _____

Report Format :

Lump Sum / I.B.I: ($ _____)

Scanned with CamScanner