



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Henderson Road Industrial Park EA Singapore 151705	
FAX Number	67665537
Estimator Telephone Number	68662623
Accident Reporting Number	68662672


Date Generated : 08/07/2020

User ID : GohKICZ

Section A - Accident Details

Registration Number	SMB226B
Case Reference Number	BUS/06/20/1056
Registration Date	14/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	CHAN KHAI PENG
Type of Accident	Head To Side
Accident Date and Time	29/6/2020 2:08 PM
Accident Reported Date and Time	29/6/2020 4:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB226B-LEFT FRONT PORTION SDZ988R (TP) INSURED WITH <i>AIG</i>
Prepared Date and Time	8/7/2020 10:05 AM
Chassis Number	WMAA22ZZXB7001200
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$1,402.50	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,424.50	\$0.00
Lump Sum Total	\$3,400.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	08/07/2020 10:10 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685492
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 09/07/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,590.00	795
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$432.00	262
Total Spray Painting & Panel Beating	\$432.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009999	BODY LH	A01001-CW555	PANEL, SIDE L5, FOR MAN A22 BUS	1.00	\$1,776.80	10.00	\$1,599.12	Replace	X R
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE DIRECT GLAZING	2.00	\$37.00	0.00	\$74.00	Replace	X SUC
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	X SUC
Total					\$1,893.80		\$1,753.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

P/P

After paint photo.

Sun Pin CLKK

09/07/2020

TP within prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: