



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007307/Ktf3s2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 20-10-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 472Y	Veh. Inspected	SMD 8800E
Policy No.		Coverage (\$)	0.00
Claim No.	C10006223	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	15/07/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X3 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBATR12000LC94116	Colour	METALLIC BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R19	PIRELLI	6 mm
L/H Front Tyre	245/50 R19	PIRELLI	6 mm
R/H Rear Tyre	245/50 R19	PIRELLI	6 mm
L/H Rear Tyre	245/50 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/03/2020	Inspection Date	20/07/2020
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------