



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS/SGK20007317/Gtf3e2	
			Date: 12/01/2021	
			Code: III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	WP1ZZZ9YZLDA04151	
Policy No.	6000872	Coverage (\$)	0.00	
Claim No.	LPL2020D0001225	Excess (\$)	0.00	
Assign From	VIKNESH	Assign Date	13/07/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PORSCHE CAYENNE	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WP1ZZZ9YZLDA04151	Colour	SILVER	
Odometer	28 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	285/40ZR21	PIRELLI	10 mm	
L/H Front Tyre	285/40ZR21	PIRELLI	10 mm	
R/H Rear Tyre	285/40ZR21	PIRELLI	10 mm	
L/H Rear Tyre	285/40ZR21	PIRELLI	10 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/06/2020	Inspection Date	15/07/2020	
Survey held at	SINGTRADE AUDIO GARAGE-160 SINMING AUTOCITY #08-02			
Repairer	-			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>10 Working Days</b>	