REC. FILE BY: GQ | REF: CS/SDK20007317/Gtf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SINGTRADE AUDIO GARAGE

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: WP1ZZZ9YZLDA04151 Yr Regn: — /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Porsche Cayenne c.c —

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 28 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WP1ZZZ9YZLDA04151 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/40ZR21

R: 285/40ZR21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	10 mm	R/Bal.	10 mm
L/Bal.	10 mm	L/Bal.	10 mm
D.O.A.		D.O.I.	15-07-2020

Survey held at W/S 12:30pm

Des. of Damage: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/07	No GIA provided
	Vehicle has been dismantled before survey and some parts been replaced.
	$28k - $30k
	unregister vehicle no LTA/GIA
	submit $28,563.96. 10days red:20819.04;42%

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

___S + RS.___SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / LPO: