

ASS. REC. BY:

REF: CS/CTI20007321/R1tf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 15/7/2020 2:53 PM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 7331Z Insured: GBG 2781E

at Workshop m/s Kok Wang Car Grooming Tel: 9183 9633

of 1 Soon Lee Street #06-40 Pioneer Centre Singapore

Policy No: Claim No: SNM20D202448

Sum Insured: Excess:

Make of Veh: D.O.A. 14-JULY-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 15-7-2020 3.22P.M

Person Contacted: Mr. Kok

Vehicle ☒ IN OUT

Date/Time	Action/Instruction (☒) Estimate
	SMD 7331Z- X
	GBG 2781E - CS/FCI19003801/Utd3n2 DOA : 25/02/2019