| ASS. REC. BY: RASM REF: CS/CTI 2000           | 7325/ f3   1522   |
|---|---|
|   | GNMENT  |
| •   | 2017 1061   |
| From: Date:                                   | Veh No: SLV 783K Yr Regn: 76/1/1000                                 |
| OD (TP) WS / TP RES / OD RES / EVA / INV / MV | Truck / Trailer or  |
| To Inspect Vehicle No: SLV 783R               | Make: B.M.W 2187 COUPE LED C.C 1499                                 |
|   | Colour BLUE A/C: Insured / Std / NI / NA                            |
| al Workshop m/s Pheroamanus                   | Sp.Reading T/Radio: Insured / Std / NI / NA                         |
| of 304, MEXAMORA RD                           | Eng/No:   |
| Insured: CTI                                  | C/No: WBA 2H320 X OVB97357 .  |
| Policy No.                                    | Gen. Cond: Good / Fally Poor / Burnt                                |
| Claims No.                                    | Steering: Inorder Jammed / Leaked / Burnt or                        |
| Sum Insured: Excess:                          | Brake: (norder / Jammed / Leaked / Burnt or                         |
| (Client's Record)                             | Modi: Nil / SiRim / STD A/Rim or                                    |
| Make of Veh:                                  |   |
|   | Tyre Size: F: 228 45R17   |
| (Policy Condition)                            | R:  |
| Remark: The veh had commenced its N/S O/S     | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /     |
| repair at the time of inspection.             | TOYOTYOKO OF CONTINENT  |
| Bal. or Market Value:                         | _ Front Rear  |
| IDAC Accident Rport: Consistent?: Yes or No   | R/Balmm   |
| GIA / PR Seen: Consistent? : Yes or No        | L/Bal. 6 mm L/Bal. 6 mm   |
| Est Repairs: days Res.: Yes or No             | 0.0.A. 08 07/2020 D.O.I. 21/07/2020                                 |
| Lum Sum: % 3 Val.: Yes or No                  | Survey held at PERFORMANCE  |
| CA I DEVI I DED I 24 UDS                      | Des. of Damages : Frt I Read I OIS I NIS I UIC I Rooftop or         |
| CA / REV / REP. / 24 HRS  Vehicle: IN / OU    | т   |
| Date: Person Contacted:                       | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time   Action / Instruction            |   |
|   | · · · · · · · · · · · · · · · · · · ·                               |
|   |   |
|   |   |
| -   |   |
|   |   |
| <u> </u>                                      | · · · · · · · · · · · · · · · · · · ·                               |
|   |   |
|   |   |
| Date/Time, File Pass to? : Prell. Report      | Days Of Repair:   |
|   |   |
| Date/Time, File Return to?                    | Resurvey No. of Trip: Survey Fee:                                   |
|   | Transportation:  Site Insp (\$ ) S+RS SI                            |
| Add F   |   |
| The wind ( 5° mars)                           | : Interview (\$) Photos   |
| Repart Formal:                                | :Tech, Invs (\$) Others   |
| Lump Sum / f.B.f: (%)                         | :Weelland (\$ )   |
| _   | YOTAL   |
|   | · · · · · · · · · · · · · · · · · · ·                               |
| · ter .                                       |   |

**Performance Motors Limited** A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSa 64796624 (Motorra

Du 59/3/50

08 JUL 2020

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

55472 Estimate No. : b1 : 08/07/2020 Date Estimated

: Chua Kee Sin Prepared By

- ESTIMATE REPAIR FOR -

40000 ACCOUNT -

Cash Sales - Service

Singapore

Singapore 309892

Leong Swan Swan

17 Barker Road

CHASSIS NO. REGN. NO.

REGN. DATE

MODEL

MILEAGE

SLV783R

WBA2H320X0VB97357

21/12/2017

218iA/2

0

DESCRIPTION Replace rear bumper include remove attachment etc Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

Sundries.

|  | Tot | al Labour 1: | 2,934.00 |
|--|-----|--------------|----------|
| DESCRIPTION  | QTY | PRIC         | VALUE    |
| RUBBER MOUNTING .  | 2   | 17.70        | 35.40    |
| TAILPIPE TIP BLACK CHROME SOM  | 1   | 123.40       | 123.40   |
| REAR SILENCER ?  | 1   | 918.20       | 918 20   |
| CLAMPING BUSH D=58MM . 7   | 2   | 59.45        | 116.90   |
| SET MOUNTS PDC SENSOR REAR   | 1   | 58.90        | 58.90    |
| REAR BUMPER CARRIER ?  | 1   | 418.55       | 418.55   |
| REAR BUMPER CENTRE GUIDE .   | 1   | 61.35        | 61.35    |
| REAR BUMPER TRIM STRIP (LINE SPORT)  | 1   | 91.15        | 91.15    |
| REAR BUMPER PANEL PRIMED (LINES) de  | 1   | 1,024.65     | 1,024.65 |
| RR FLAP TOWING EYE PRIMED 500 /  | 1   | 39.15        | 39.15    |
| RIGHT PROTECT ?  | 1   | 12.85        | 12.85    |
| LH REFLECTOR ?   | 1   | 12.85        | 12.85    |
| RH REFLECTOR ?   | 1   | 37.75        | 37.75    |
| PDC sensor ?   | 1   | 37.75        | 37.75    |
| DECOUPLING RING PDC TORQUE CONVERTE ?  | 4   | 370.00       | 1,480.00 |
| THE PROPERTY OF THE PROPERTY O | 4   | 5.10         | 20.40    |
|  | To  | tal Parts :  | 4,491.25 |

APR

NA

NA

VALUE 1,028.00

9<sub>150.00</sub>

#### Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road Bast Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Pax. 64796601 (AfterSa) 64796624 (Motorrac (AfterSales)



ADIC

NA

NA

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. 55472 : b1 Date Estimated : 08/07/2020 prepared By : Chua Kee Sin Page No. : 2 of 5

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SLV783R

WBA2H320X0VB97357

21/12/2017

218iA/2

0

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| Claims OD / 3rd Party / Unins | ured losses / Direct Settlement |
|-------------------------------|---------------------------------|
| Rean No.                      | 0.000                           |
| Date&Time 21 07 2020 @        | 1355 Excess S\$                 |
| Surveyor's Name R48WL         | Sian                            |
| Surveyor's Tel 900 LOOF &     | Authorised Yes / No             |
| Authorised Date               | Time                            |
| RESURVEY PARTS PHOTO BY SUF   | RVEYOR Yes / No PML Yes / No    |
| Surveyor's E-mail             | - FINE TEST NO                  |
| No. of Working Days Recommend | 3 days                          |
| D = 1                         |                                 |
| Lr. 2) 9                      | afore paint                     |



Labour 1 2,934.00 Parts 4,491.25 Labour 2 0.00 Excess 0.00 Total GST @ 7% 519.77

Grand Total

7,945.02

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

20057965 / Performance Motors Limited - Alexandra 0057965 / Performance Motors Lli DATE & TIME: 08/07/2020 15:51 TED BY: Melanie Setiawati

#### SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE IMPURITY IN PROJECT THE PROJECT OF T

1. Please or must be completed by the Policyholder and/or the Authorised Driver.
2 This Form must be completed by the Policyholder and/or the Authorised Driver.

repudiate policy liability.

repudition From the insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. Any raise.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for a raise and that copies of this report will, for a fee, he made available upon configuration. 6. This report that copies of this report will, for a fee, be made available upon application by interested parties.

archiving the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT:

Date Of Report 08/07/2020 15:51 08/07/2020 07:30 Date Of Accident

TANGLIN ROAD OPPOSITE GRACE ASSEMBLY CHURCH **Exact Location Of Accident** 

NO

SINGAPORE Country/State of Loss

II DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV783R

Insured/Policyholder

LEONG SWAN SWAN Name Of Registered Owner

SXXXX152Z NRIC No

LEONGSWANSWAN@GMAIL.COM **Email Address** 

(LOCAL) +65-81232668 Mobile Phone No OTHERS-81232668 Alternative Phone No

Vehicle Particulars

**BMW** Manufacturer 218IA

Model

Exact Purpose for which vehicle was being used at NORMAL USAGE time of accident

Are you claiming under your own insurance policy

for repair to your vehicle? THIRD PARTY

If No, Please state action to be taken PRIVATE CAR

Vehicle Category

**Insurance Company** AXA INSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

**UNAVAILABLE** Policy Number

Cover Note Number

Driver

LEONG SWAN SWAN Name of Driver

NRIC No SXXXX152Z Date Of Birth 10/10/1963 INDOOR Occupation Date Of Driving Pass 27/04/1982

**Driving Experience** 38 YEARS AND 2 MONTHS

**FEMALE** Gender

(LOCAL) +65-81232668 Mobile Number

Fax Number

OTHERS-81232668 Contact Number

LEONGSWANSWAN@GMAIL.COM **EMail Address** 

| driver an employee of the Insured's Company No. Relationship of the Driver with the Insured vehicle Registration Number of Driver's Own vehicle | 17 BARKER ROAD<br>309892<br>NO<br>OWNER |
|---|---|
| Insurance Company of Driver's Own Vehicle   | •<br>•                                  |
| General Information of the Accident   |   |
| Type Of Accident  | COLLISION - HEAD                        |

ION - HEAD TO REAR Weather Conditions CLEAR Road Surface DRY

Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) 2 involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by NO ambulance? Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

#### **Details of Police Action**

NO Was the accident reported to the police? If Yes, Please state which Police Station NO Was notice of intended Prosecution given?

Number of Passengers (Including Driver)

#### If Yes, against whom? **Circumstances of Accident**

# REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO Was there any audio recorded?

## IDETAILS OF OTHER VEHICLE PROPERTY

PRIVATE CAR

SJW9000B Vehicle Registration Number **BMW WHITE** Vehicle Make/Model/Colour **Details Of Properties** 

LEE QIANG JOSHUA Name of Driver

SXXXX572Z NRIC/Passport Number 90680024 Contact Number

Address Postcode

Vehicle Category

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Insurance Company Name

**FRONT** Nature Of Damage

No. Of Passenger (Including Driver)

### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

8/7/2021

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

|  | Date: 8 July 2020.  I was travelling along Taughin Road towards Orchard Road at about 7 I stopped at traffic lifer as it turned red, opposite Grae Assembly Church I than felt a Sudden fork and board a borry! | DESCRIBE CIRCUMSTANCES OF THE ACCIDENT |
|--|---|--|
|--|---|--|

Polityholder's Signature
Date & Time: & 7 | Turns
2-41 Pm

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Perponel's Signature
Name:
NRIC/FIN No.:





# gov.sg/lta/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION\_ID=F0304009

# > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type:                | Singapore NRIC        |
|-------------------------------|-----------------------|
| Owner ID:                     | 152Z                  |
| Vehicle No.:                  | SLV783R               |
| Vehicle to be Exported:       | No.                   |
| Intended Deregistration Date: | 21 Jul 2020           |
| Vehicle Make:                 | B.M.W.                |
| Vehicle Model:                | 218I COUPE LED NAV SR |
| Primary Colour:               | Blue                  |
| Manufacturing Year:           | 2017                  |

| Engine No.: 38                 | 915115B38B15A    |
|--------------------------------|------------------|
| Ligite 1402                    |                  |
| Chassis No.: Wi                | BA2H320X0VB97357 |
| Maximum Power Output: 10       | 0.0 kW (134 bhp) |
| Open Market Value: \$3         | 0.907.00         |
| Original Registration Date: 21 | Dec 2017         |
| First Registration Date: 21    | Dec 2017         |

Transfer Count: \$30,270.00 Actual ARF Paid:

#### ■ teresistetere@tiente≌ (eniberea @felicit

| PARF Eligibility:             | #20pt | Yes         |
|-------------------------------|-------|-------------|
| PARF Eligibility Expiry Date: |       | 20 Dec 2027 |
| PARE Rehate Amount:           |       | \$22,702.00 |

| COE Expiry Date:     | 20 Dec 2027                           |
|----------------------|---------------------------------------|
| COE Category:        | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):   | 10                                    |
| QP Paid:             | \$53,711.00                           |
| COE Rebate Amount:   | \$39.811.00                           |
| Total Rebate Amount: | \$62,513.00                           |
|                      |                                       |

The information contained herein is correct as at 21 Jul 2020