ASS. REC. BY: RASH	GNMENT
From: Date:	Veh No: SW 783R Yr Regn: 2017 / OEC
Estimated Cost:	Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLV 783R	Make: B.M. W 218 I COUPE LED C.C 1499
at Workshop m/s Pheroamenus	Colour BLUE A/C: Insured / Std / NI / NA
of 303, proxxnora Ro	Sp.Reading 1864 T/Radio: Insured / Std / NI / NA
Insured: CT1	Eng/No:
Policy No.	C/No: WBA 24320 X UVB97357 .
Claims No.	Gen. Cond: Good / Fally Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnit or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
	Tyre Size: F: 225 45 R (7
(Policy Condition) Remarks The stab had commenced its	R;
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO Or ON TOYONTO
Bal. or Market Value: 10 K	_ Front Rear R/Bal. (mm
DAC Accident Rport: Consistent? : Yes or No	1/201
GIA / PR Seen: Consistent?: Yes or No	D.O.A. 08 07 2020 D.O.I. 21/07/2020
Est Repairs: days Res.: Yes or No	Survey held at DERFORMANCE
	Des. of Damages: Frt Read O/S N/S U/C Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN/OU	
Vehicle: IN/OU Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
·	
	0.044545455
	\$ 3,445.15/3DAYS WITH KEITH
(\$ 4,033.15/RED - 54%)	
- <u>;</u>	
X ·	
. 35 3.200 10 -	
ale/Time, File Pass to? 12/08/2020: Prell. Report	Days Of Repair:3
TYPIST : Final Report	Resurvey No. of Trip: 1 Survey Fee:
ate/Time, File Return to?	Transportation:
Add F	ee: : Site Insp (\$)s +Rssi
	: Interview (\$)) Photos
e e)] Min(08
epara Formes:	: Tech, Invs (\$) Others