

REF: CS/TMI20007344/Dvg3

ASS. REC. BY:

ASSIGNMENT

C02 Oct 2020

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

T6K10 OD TATA LOSS

Vehicle Damage abt 3 months at time of loss.

MV = Perf + body

= 18.2K + 5K

= 23K

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) 21/7/20-Typist

Report Format : _____

Ext-T/L

Lump Sum / L.B.I. (\$ _____)

Veh No: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Estima

C.C. 2362

Colour _____

A/C: Insured / Std / NI / NA

Sp. Reading _____

H.A.

T/Radio: Insured / Std / NI / NA

Eng/No: _____

2AZC915101

C/No: _____

ACR500120756*

Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: 225/45 R18

R: _____

Michelin

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

mm

6

R/Bal. _____

mm

6

L/Bal. _____

mm

6

L/Bal. _____

mm

6

D.O.A. 14/07/2020

D.O.I. _____

16/07/2020

Survey held at

Tai Huet Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

The vehicle caught fire at the

The U/C / Chassis frame / Body Structure affected due to collision.

engine compartment.

Cause of fire due to electrical

wire to the battery cable.

MV 23K

LA 19.4K

NL 3.6K

SCDF \$170

Days Of Repair: _____

Investigation \$500

Resurvey No. of Trip: _____

Survey Fee: _____

1) Date/Time, File Return to?

Transportation: _____

2) 21/7/20-Typist

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Photos

Others

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity

160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722

Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg

UEN: 199407592C

INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	TOTAL LOSS
Policy No:	19-MU011282-R02	Date of Loss:	14/07/2020
Vehicle Reg. No.:	SJZ1578M	Driveable?	NO
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	LIM KOK PING (LIN GUOBIN)	Contact No:	+6597475740
Driver:	LIM KOK PING (LIN GUOBIN)		

Make/Model: TOYOTA ESTIMA AERAS, 2.4 PREMIUM (A)
Vehicle Colour: SILVER
Engine No: 2AZC915101
Odometer: 0 KM

Vehicle Reg. Date: 29/10/2010
Gen Condition: GOOD
Chassis No: ACR500120756

Paint Type:
Total Loss? YES

Est. Duration of Repair (day) 0

Description of Accident/Loss

REFER TO SKETCH PLAN / POLICE REPORT NO: E/20200714/7048

Present Location:

LAI HUAT (MENG KEE) MOTOR PTE

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	11.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total: (S\$)	11.00
+ GST 7.00% (S\$)	0.77
Nett Amount (S\$)	11.77

16/07/2020 e 1638hrs

WRT Accident

TOTAL LOSS.

Excess TBA.

This claim is handled by: JENNY LIM LAI FOONG

[Signature]
JLK Audio

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Pending fire investigation.