

ASS. REC. BY: Taughlin

REF:

QBE

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMC87755 Yr Regn: 2015 Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 863503 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHUK 41447 G4080757Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 14/7/20.Survey held at Comfordelgno Weying

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roadtop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. ~~of~~ Format: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

COMFORTDELGRO ENGINEERING

Member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline - 65 6363 6280 Facsimile - 65 6280 9755

Workshops

55 Loyang Drive Singapore 500968

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 600096

24 Serangoon Road Singapore 556158

7 Sungei Kadut Drive Singapore 718151

501 Manul Industrial Park 4 Singapore 1587

Date/Time: 14.07.2020 10:08

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.:305410694

MEMER

COMFORT TRANSPORTATION PTE LTD

7010045

MEMER NO.

SS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

R)

P)

UNT CARD NO.

REGN NO.

SHC8775J

MILEAGE

MAKE :

HYUNDAI

FUEL

E 1/2 F

MODEL

I-40

DATE TIME IN

13.07.2020 16:05

YR OF MANU.

03.12.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMGU080757

COMPLETION DATE TIME

JOB DESCRIPTION


Accident Date: 13.07.2020

ATURE: 3P 13.07.2020

Y NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.:

SHC8775J

SHC8775J

JU QBE LKK

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard