

QRE - (Lsum)

JM

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.07.2020

Time: 10:14:46

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305410694
 REGN NO : SHC8775J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 03.12.2015
 DATE/TIME IN : 13.07.2020 16:05
 ACCIDENT DATE : 13.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00 25.00 829.50 <i>dev</i>
0002	04-01-0103-0585-A	LAMP ASSY-RR COMB O/S RH#	1	697.80 25.00 523.35 <i>as</i>
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00 25.00 16.50 <i>as</i>
0004	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00 2.50- 50.00 <i>all</i>
0005	04-01-0103-0783-G	BRKT ASSY-RR BUMPER SIDE	1	35.60 25.00 26.70 <i>?</i>

SUB-TOTAL : 1,446.05

JOB NATURE

0000 PB	PANEL BEATING	300.00	<i>280</i>
0001 SP	SPRAYPAINT CHARGE	300.00	<i>200</i>
0002 17-01	CHECK ALL LIGHTING	50.00	<i>30</i>
0003 L	REMOVE/REFIX REVERSE SENSOR	80.00	<i>30</i>

SUB-TOTAL : 730.00

Tanji 97445746
WP
14/7/20 @ 2pm
02 days before repair
Resurvey after repair
Tanji @ Wharfedale

Lkk Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: