

Our Job Ref No 305410694

Date : 15/07/2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : TAUFIKH

: SHC8775J

DOA: 13/07/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: QBE --- YN 7217C  
###
2. The finalized amount shall be:
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges ### \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \_\_\_\_\_  
###
- (c) Lumpsum Repair (if applicable) N \_\_\_\_\_
- Total for Lumpsum repair cost after Less: 20% ~~\$1,650.00~~ \$1600
- Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Taufikh

Date : 16/7/20

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: