

ASS. REC. BY:

REF: CS/CTI20007360/Gvf3

Special Instruction:

Surveyor: GQASSIGNMENT (Office)From (Person): CECILIA LOHof CTIDate/Time: 16/7/2020 3:09 PM

Estimated Cost: _____

Bill to: _____

OD-☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLM 708GInsured: SGC 985Jat Workshop m/s BIFROSTTel: 9329 0237of 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki BukitPolicy No: DMPCSNA00000412001Claim No: SNM20D202418

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 12/07/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 16-7-20 3.22P.MPerson Contacted: IKHWANVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLM 708G- NA/CTI20007235/z4 DOA :12/07/2020
	SGC 985J - NA/CTI20007235/z4 DOA : 12/07/2020
17/7/20	Send IA via merimen, pending parts prices from repairer
30/9/20	Send IA via merimen
30/9/20	LS \$3200 confirmed (Red 12,184.33, 79%)