

ASS. REC. BY:

REF: C72/20007361/Hs Ksf3


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Kang Arto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 880k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

☐: Preli. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech Invs (\$ _____)☐: Weekend (\$ _____)

Survey Fee:

Transporta/Forc:

\$ - RS \$

Fees

Others

TOTAL

Veh No: SNC 4134 Yr Regn: 06, 12Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mu GLS 350 c.c. 3498Colour: M. Black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 92218 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WDD 2183592A 032560Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inopdr / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inopdr / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ NII / ☐ S/Rlm / ☒ STB A/Rlm orTyre Size: F: 245/40R19R: 275/35R19BS: ☒ BUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 6 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 11/7/20D.O.I. 16/7/2020

Survey held at

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop orRear O/S & O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Sp

• N

KANG

AUTO ENGINEERING PTE LTD



Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

Not Authorised

6/1 Bng B?
After Paint

M/S Mr Lim Chin Sheng Alex
15 Yishun Central 1
#04-20
Singapore 768797

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP20/07/1148
VEHICLE NO : SMC413Y
MAKE/MODEL : Merc Benz CL350 (A)
DATE OF ACCIDENT : 11-Jul-20

- 1 PC BONNET *R A*
- 1 PC BONNET LOCK *R A*
- 1 PC FRONT BUMPER *R A*
- 1 PC FRONT BUMPER BADGE *new*
- 1 PC FRONT BUMPER GRILLE *CM*
- 1 PC FRONT BUMPER GRILLE BADGE *?*
- 1 SET FRONT BUMPER CLIPS *new*
- 1 PC FRONT BUMPER LOWER GRILLE *CM*
- 1 PC FRONT BUMPER O/S SIGNAL LAMP *Bn*
- 1 PC FRONT BUMPER TOWING COVER *new*
- 1 PC FRONT BUMPER SIDE RETAINER *P.1*
- 1 PC FRONT BUMPER REINFORCEMENT *Rt*
- 2 PCS FRONT BUMPER BRACKETS *cls Bn*
- 1 PC FRONT BUMPER ENGINE DUST COVER *new*
- 2 PCS FRONT BUMPER CHROME *new*
- 1 SET FRONT SENSORS *new*
- 2 PCS HEADLAMP ASSY *cls Bn*
- 1 PC HEADLAMP BRACKET R/H *?*
- 1 PC FRONT APRON PANEL *?*
- 1 PC FRONT SUPPORT PANEL (CENTRE) *?*
- 1 PC FRONT R/H FENDER *Buc*
- 1 PC FRONT R/H FENDER INNER SHIELD COVER *Tn*
- 1 PC AIR CLEANER IN-TAKE HOUSE *?*
- 1 PC RADIATOR ASSY *?*
- 1 PC RADIATOR AUTO FAN ASSY *?*
- 1 PC RADIATOR PIPES *?*
- 1 PC AIR CON CONDENSOR *?*
- 1 PC AIR CON COMPRESSOR *?*
- 1 PC AIR CON COOLING PIPE (ALUMINIUM) *?*
- 1 PC AIR CON DISCHARGE PIPE *?*
- 1 PC AIR CON SUCTION PIPE *?*
- 1 PC FRONT ENGINE MOUNTING *?*
- 1 PC REAR BUMPER *Tn*
- 1 PC REAR BUMPER MOULDING *new*

Specialised In :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg



M/S Mr Lim Chin Sheng Alex
15 Yishun Central 1
#04-20
Singapore 768797

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP20/07/1148
VEHICLE NO : SMC413Y
MAKE/MODEL : Merc Benz CL350 (A)
DATE OF ACCIDENT : 11-Jul-20

1 PC REAR BUMPER SENSOR *dis*
1 PC REAR BUMPER LOWER LID *dis*
2 PCS REAR BUMPER BRACKETS *dis*
1 PC REAR BUMPER REINFORCEMENT *dis*
1 PC REAR BUMPER INNER GRILLE ?
1 SET REAR BUMPER CLIPS *dis*
1 PC REAR BUMPER SIDE RETAINER *dis*
1 PC TAILLAMP ASSY (RH) *dis*
1 PC REAR EXHAUST SILENCER *dis*
1 PC REAR EXHAUST COVER ?
1 PC REAR EXHAUST MUDFLAG ?
1 PC REAR R/H FENDER *dis*

1 SET REVERSE SENSOR
2 PCS FRONT & REAR RH TYRES
1 SET FRONT & REAR RH TYRE RIMS
2 PCS FRONT & REAR NUMBER PLATE

SS\$ 400.00 S'NETT ?
1,200.00 508.50
2,400.00
150.00 45.50

TOWING CHARGE
TO CHECK WIRING
TO RE-SET ENGINE
TO REMOVE & REFIT REAR WINDSCREEN
TO REMOVE & REFIT AIR CON CONDENSOR & TOP UP GAS
TO REMOVE & REFIT EXHAUST SILENCER
TO RESET WHEEL ALIGNMENT
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL
TO PUTTY AND SPRAY PAINT
LABOUR CHARGES

(Bill) SS\$ 150.00 ?
50.00 40.00
350.00 ?
250.00 X
180.00 100.00
250.00 80.00
180.00 120.00
160.00 30.00
2,500.00 1200.00
3,000.00 1100.00

SS\$ 11,220.00

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 14/07/2020 15:24
Date Of Accident 11/07/2020 03:30
Exact Location Of Accident CTE (SLE) TUNNEL
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC413Y
Insured/Policyholder
Name Of Registered Owner LIM CHIN SHENG ALEX
NRIC No SXXXX621H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98866118
Alternative Phone No OFFICE-98866118

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model CLS350-3.5 (A)
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA370259
Cover Note Number

Driver

Name of Driver LIM CHIN SHENG ALEX
NRIC No SXXXX621H
Date Of Birth 07/03/1965
Occupation INDOOR
Date Of Driving Pass 26/09/1983
Driving Experience 36 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98866118
Fax Number
Contact Number OFFICE-98866118
EMail Address NOEMAIL

Address 15 YISHUN CENTRAL 1 #04-20
 Postcode 768797
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8522999 - FAX NO: 68522239
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORTS


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMS112G
 Vehicle Make/Model/Colour NISSAN GTR
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver BOON JUN XIAN
 NRIC/Passport Number SXXXX417G
 Contact Number 96882345
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- AS per police REPORT -
 T/20200714/2029 (amended)
 T/20200711/2043

* Third Party claim @ Kang Auto
 Email my accident report to them

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature


Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 621H

Vehicle Details

Vehicle No: SMC413Y
Vehicle to be Exported: No
Intended Deregistration Date: 20 Jul 2020
Vehicle Make: MERCEDES BENZ
Vehicle Model: CLS 350
Primary Colour: Black
Manufacturing Year: 2011
Engine No: 27695230070385
Chassis No: WDD2183592A032560
Maximum Power Output: 225.0 kW (301 bhp)
Open Market Value: \$82,655.00
Original Registration Date: 28 Jun 2012
First Registration Date: 28 Jun 2012
Transfer Count: 2
Actual ARF Paid: \$82,655.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jun 2022
PARF Rebate Amount: \$45,460.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$85,216.00
COE Rebate Amount: \$16,498.00
Total Rebate Amount: \$61,958.00

The information contained herein is correct as at 13 Jul 2020

OK