

ASS. REC. BY: ASUL

REF:

CC3/AIG 20007370/ KS3


2224

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJP 1976A
at Workshop m/s Volkswagen
of 17, MAS ME 1
Insured: AIG
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 106K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 1976A Yr Regn: 2017 / OCT
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: VOLKSWAGEN SHARAN 2.0 TDI cc 1984
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 50048 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: WVW ZZZ 7NZ JV 002805

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt or _____Brake: ☒ In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/50 R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 15/07/2020 D.O.I. 20/07/2020

Survey held at VOLKSWAGENDes. of Damages: ☒ Front ☒ Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 40K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

Rep. Format: _____

Lump Sum / F.B. (\$) _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	222H
Vehicle No.:	SJP1976A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jul 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI 7N24MY
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	DED015086
Chassis No.:	WVWZZZ7NZJV002805
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$34,839.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$40,775.00
Information on PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2027
PARF Rebate Amount:	\$30,581.00
Information on COE Eligibility	
COE Expiry Date:	30 Oct 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,005.00
COE Rebate Amount:	\$34,932.00
Total Rebate Amount:	\$65,513.00

The information contained herein is correct as at 20 Jul 2020

OK

► Volkswagen Sharan 2.0A TSI Sunroof

Mad

Don't look no further to this Continental 7 Seater Spacious MPV, with Sunroof And High

