

ASS. REC. BY:

REF:

FWD/20007380/KJ

Henneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

3/22

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGU 4942L Yr Regn: 05, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

c.c

1897

Colour

White / Black

A/C:

Insured / Std / NI / NA

Sp. Reading

200.276

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR05314Y9305000977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R13

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

15/7/20

D.O.I.

17/7/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S 151

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got injury

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S + RS. SI

: Photos

: Others

Report Format:

Lump Sum / I.B.I: (\$

TOTAL