

ASS. REC. BY:

REF: CS3/CTI20007383/Gtf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Cecilia Low of CTI Date/Time: 17 Jul 2020 00:39

Estimated Cost: Bill to:

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 1390D Insured: SJH 2973T

at Workshop m/s King's Auto Repair & Service Pte Ltd Tel: 64578629

of BLK 176 SIN MING DRIVE, #02-10

Policy No: DMPCSN30552419011 Claim No: SNM20D202450

Sum Insured: Excess:

Make of Veh: D.O.A. 13/07/2020
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17-7-20 9.46A.M Person Contacted: ANDREW Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SLW 1390D- X
	SJH 2973T- CS/CTI19014551/Hvf3e2 DOA : 24/07/2019