


ASS. REC. BY: Sun Pin REF: NTUC NS/INC20007386/Qqf3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. MT/1096632-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 261 Yr Regn: 07/11/2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Tractor or _____
 Make: Mercedes Benz OC500LE c.c. 11967
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 966873 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WEB 63442021000087
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / A/Rim or
 Tyre Size: F: 275/70 R22-5
 R: 275/70 R22-5
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or 3 Falken
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 10/07/2020 D.O.I. 15/07/2020
 Survey held at SMRT
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/08/20 @ 5.44pm	Sun Pin finalised with Catherine LS \$1650, 3 days. (Red \$4945.80, 75%)

Date/Time, File Pass to? ☐ : Prel. Report

1) 21/08 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum 1650

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Police _____

Others _____

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB26L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	OC500LE1830H
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	45796600172687
Chassis No.:	WEB63442021000087
Maximum Power Output:	-
Open Market Value:	\$319,861.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$15,994.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 16 Jul 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/07/2020 15:56
Date Of Accident	10/07/2020 16:40
Exact Location Of Accident	ADMIRALTY LANE JUNCTION WITH CANBERRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB26L
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXXX292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	MBOC500
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095488MFBP
Cover Note Number	
Driver	
Name of Driver	TAN KIAN SOON
NRIC No	SXXXXX070G
Date Of Birth	14/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	06/01/2014
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 15

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

On 10/07/2020 at 1640 hrs, I was driving SMB26L, Svc 859. I was turning right at the controlled signalized junction from Admiralty Lane to Canberra Road. I was turning at 20 km/h with 15 pax onboard. When I initially turned right, I did not see any car on my right, as it was from one lane turning to 2 lanes. As I was about to complete the right turn, I saw a car on my right rear and it knocked on the right rear side of my bus. I heard a sound. I stopped the bus ahead and alighted to check and found scratches on the right rear side of my bus as well as the front left of the car. There were no injuries reported. That's all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMS1452T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

SMB262
pax = 15
Bus/07/20/1011

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-ordinate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


X
Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2


SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT *Admiralty Lane junction with
Canberra Road.*

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63685592
Estimator Telephone Number	69662623
Accident Reporting Number	88662672


Date Generated : 15/07/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB26L
Case Reference Number	BUS/07/20/1011
Registration Date	11/11/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Tan Kian Soon
Type of Accident	Side Swipe
Accident Date and Time	10/7/2020 4 40 PM
Accident Reported Date and Time	10/7/2020 5 45 PM
Is Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB26L-RIGHT REAR PORTION SMS1452T (TP) INSURED WITH NTUC
Prepared Date and Time	14/7/2020 4 47 PM
Chassis Number	WEB63442021000087
Allegae	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$942.00	\$0.00
Total Spare Part Cost	\$160.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,427.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	14/07/2020 4:58 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 15/07/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,325.00	1060
Total Labour	\$1,325.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$942.00	772
Total Spray Painting & Panel Beating	\$942.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace / Nec
010227	BODY RH	5019	PANEL SKIRT R4, FOR MB OC500 BUS	1.00	\$1,442.10	100.00	\$0.00	Repair	X R
010229	BODY RH	5021	PANEL SKIRT R6, FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Repair	X R
010230	BODY RH	5022	PANEL SKIRT R7, FOR MB OC500 BUS	1.00	\$880.50	100.00	\$0.00	Repair	X R
010231	BODY RH	5023	PANEL SKIRT R8, FOR MB OC500 BUS	1.00	\$338.10	100.00	\$0.00	Repair	X R
010232	BODY RH	5024	PANEL SKIRT R9, FOR MB OC500 BUS	1.00	\$307.10	100.00	\$0.00	Repair	X R
010234	BODY RH	5026	PANEL SKIRT R11, FOR MB OC500 BUS	1.00	\$642.80	100.00	\$0.00	Repair	X R
Total					\$4,328.80		\$200.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days

Sun Pin (Lick)

15/07/2020

TP without prejudice.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary Item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: