

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHF130G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS100824
Chassis No.:	JTDKB3FU603573451
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$22,216.00
Total Rebate Amount:	\$25,966.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jul 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2020 09:43
Date Of Accident	14/07/2020 18:30
Exact Location Of Accident	WOODLANDS AVE 6 TOWARDS WOODLANDS AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF130G
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095484MFSH
Cover Note Number	

Driver

Name of Driver	LEAN CHEONG SOON
NRIC No	SXXXX961C
Date Of Birth	26/01/1962
Occupation	OUTDOOR
Date Of Driving Pass	30/05/1994
Driving Experience	26 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 3
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 4
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20200714/2100

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM1248D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ANG POH HUAT
NRIC/Passport Number	SXXXX254C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ANG POH HUAT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

A - St
B - FB

B - FBM 1248D .

This is a blank sheet of white paper with horizontal black ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.

der's Signature

Driver's Signature

15/7/2020

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured the vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20200714/2100

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No 1800-6659999

1 of 3

Report No. T/20200714/2100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2020 21.09	Vide Report No.: L/20200714/0132	Station Diary No.: 139
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LEAN CHEONG SOON			Address: APT BLK 453A BUKIT BATOK WEST AVENUE 6 #18-753 SINGAPORE 651453	
ID Type / ID No.: NRIC NO / S1560961C			Contact No.: Home/Office: Mobile: 91076067	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 58	Date of Birth: 26/01/1962	Type of Informant: Driver	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/07/2020 18:30	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS AVENUE 6 WOODLANDS AVENUE 1 Along Woodlands Avenue 6 towards Woodlands Ave 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Controlled by Others e.g. Workmen		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM1248D	Motorcycle	HONDA	CBF190X		Slightly Damaged	0
SHF130G	Car	TOYOTA	Prius	Maroon	Slightly Damaged	4

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**



T/20200714/2100

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20200714/2100

CONTINUATION OF REPORT

Rider			
Name	ANG POH HUAT		ID No. S6828254C
Related Vehicle	FBM1248D (Motorcycle)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEAN CHEONG SOON		ID No. S1560961C
Related Vehicle	SHF130G (Car)		Contact No. 91076067
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 14/07/2020 at about 1830hrs, I was driving my taxi, SHF130G, along Woodlands Avenue 6 towards Woodlands Avenue 1, I was ferrying 4 passengers, a couple along with 02 children, I wanted to turn right into the carpark entrance of a HDB Block as it was the address of my passenger. I then signal right to show my intention to turn right and my vehicle came to a halt as there was oncoming traffic coming from the opposite direction.

The next moment, there was an impact from the rear of my taxi, I then alighted from my vehicle to make a check and realized that a motorcycle, FBM1248D, had collided onto the rear of my vehicle. The rider had fell onto the ground. I then called for the ambulance. I then took photos of the scene and went to assist the rider. The Traffic police and the ambulance came and convey the rider to the hospital. I wish to state that there is in car camera in my vehicle and the footage has been taken by traffic police. My passengers did not complained for any injury at that point of time. I was advised to lodged a Police report under IO Rahim. I only have some slight aches due to the collision..

Due to the accident, Rear windscreen and Rear Boot were damaged.

Sketch Plan Pg. 5



**SINGAPORE
POLICE FORCE**



T/20200714/2100

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20200714/2100

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt LEE JUN XIANG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/07/2020 21:09

Officer In Charge Of Case:

TP / GIT /

Sgt 3 ABDUL MUHAIMIN BIN HUSSAIN

Contact No.: 65476845

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE
SAFEGUARDING EVERY DAY

SIGNATURE



Case Details

Case Reference Number :
TAX/07/20/2025
Type of Repair : Accident Repair
Vehicle Registration Number :
SHF130G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-12061-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
Accident Date and Time : 14/07/2020 10:30 AM
Vehicle Age(In Months) : 32

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ / CR4
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ / Nec
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓ X Svc
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / Nec

Total Spare Part Cost 10,574.87

Surveyor Total 2,997.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,459.90

Final Sur Total 2,397.64

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.83	Replace	1	83.83	Replace	✓/BR
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	1	4.30	4.30	25.00	3.22	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	✓/MIS
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓/CR4
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	✓/Nec
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	✓/CR4
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	1	175.73	Replace	✓/cut
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace	✓/CRA
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	27.90	25.00	20.92	Replace	0	0	Not Give	✓X Svc
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	0	0	Not Give	✓X Svc

Total Spare Part Cost 10,574.87

Surveyor Total 2,997.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,459.90

Final Sur Total 2,397.64

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	725.90	25.00	544.42	Replace	1	544.42	Replace	✓ BR
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	27.90	25.00	20.92	Replace	1	20.92	Replace	✓ NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	✓ NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	✓ NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	1	14.77	Replace	✓ NEC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ NEC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	✓ NEC
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	✓ NEC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	✓ NEC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ NEC
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	✓ X R
One Time Key In	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	✓ SVC
Total Spare Part Cost									10,574.87	Surveyor Total 2,997.05				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									8,459.90	Final Sur Total 2,397.64				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			BOX, DECK FLOOR, LH	1	303.40	303.40	25.00	227.55	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	✓ / CRU.
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	1	40.50	Replace	✓ / SCR
One Time Key In	Main			TROUGH, BACK DOOR , LH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	✓ X SVC
Total Spare Part Cost									10,574.87	Surveyor Total			2,997.05	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									8,459.90	Final Sur Total			2,397.64	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	1,014.00	400	✓
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	/
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	100	/
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
4	Main	TO RESPRAY TAIL GATE	378.00	0	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	/
6	Main	TO RESPRAY REAR SPOILER	180.00	100	/
7	Main	TO RESPRAY REAR PANEL	180.00	0	
8	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
9	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
10	Main	TO RESPRAY REAR FENDER LH	378.00	0	
11	Main	TO RESPRAY RIM	180.00	0	
Total:			2,574.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	/
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	475.00	125	/
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	/
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
Total:			1,975.00	305.00	

15/07/2020

https://vacswed.smrt.com.sg/estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
10	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	
11	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
12	Main	TO REPLACE SUNDRY PARTS	100.00	0	
13	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,975.00	305.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,459.90	2,397.64
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,574.00	500.00
Other	1,975.00	305.00
Overall Total	14,022.90	3,602.64
Lump Sum Repair Option		☒
Lump Sum Total	14,000.00	3,600.00
Surveyor Approved Amount		3,600.00
No of Repair Days*	8	3 <i>3 days</i>
Remarks	-	L/S. after paint photo

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

15/07/2020