

22/03/2019

ASS. REC. BY:

REF:

CS3/MSG19021551/Eqf3-1

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Chhwa Myut Pui

of MSIG

Date/Time: ~~6.12.19~~ 18/07/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 3416 C

Insured:

GBF 9425 T

at Workshop m/s Zoom Autoworks

Tel:

9450 7920

of 130 Bedok Reservoir Rd #08-1339

Policy No: 29075029 MKC

Claim No:

613559

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 6.12.19 10.46a.m

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: BIK 15 Telok Bukit Rd 4 #01-53
	GBF 9425 T: NA/INC 19021510/24 DOR: 04/12/2019
	SMK 3416 C: NA/INC 19021510/24 DOR: 04/12/2019
10/12/19	11.06am checked with Elin, they will not provide us estimate.
	6/12/19 - survey taken
	21/1/20 - after paint taken.
21/1/20	Submit PRS.

21/07/20 Submit LS \$2750, 3 days (Red \$2550, 48%)

ASS. FILE BY: H-ANN

REF: M516

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

Smk 3416 C Yr Regn: 2/07/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Smk 3416 C

Make:

Ford Mustang

c.c

2261

at Workshop m/s

200m Auto works

Colour:

Grey

A/C: Insured / Std / NI / NA

of

B1/K 15 Kalia Sub rd 4

Sp. Reading

028097km

T/Radio: Insured / Std / NI / NA

Insured:

#01-53

Eng/No:

Policy No.

C/No:

1FA6P8TH9G5300984

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

Tyre Size:

F:

255/40/2R19

R:

255/40/R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

4/12/17

D.O.I.

6/12/17

Survey held at

200m Auto works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range → 2-3 km

rpr days → 3 days

* Smk 3416 C

PRS case

2/1/2020

MV - 154000

PV - 76973

NV - 77000

RECEIVED 21 JAN 2020

Eilan → 74507920

Date/Time, File Pass to?



: Prell. Report

to 21/1/2020



: Final Report

Date/Time, File Return to?

3

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Parking

Others

Total

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Wash and (\$

Report Form:

MER-TP

Lump Sum (USD):

2750

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2019		06 Dec 2019 10:34 Assign				New Assignment Cancel Case

Main Reference Claim Details Documents Show All

CLAIM SUBFOLDER DETAILS

CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	JONG FRESH SUPPLIES PTE LTD, Co. Reg. No.: 200107204H		
Main Claimant:	ONG LAY TIN, ID: S6802144H		
Vehicle Reg. No.:	SMK3416C	Date of Loss:	04/12/2019 11:00 - :59 [38 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 613559	Policy/Cover Note No.:	29075429MKC (Comprehensive) Coverage: 10/04/2019 - 09/04/2020
Vehicle Reg. No. (Insured):	GBF9425T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/12/2019]		
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Elin Cai @ 9450 7920.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2019 09:09
Date Of Accident	04/12/2019 11:50
Exact Location Of Accident	JUNC CHULIA ST & SOUTH CANAL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK3416C
Insured/Policyholder	
Name Of Registered Owner	ONG LAY TIN
NRIC No	S6802144H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81831081
Alternative Phone No	OFFICE-81831081

Vehicle Particulars

Manufacturer	FORD
Model	MUSTANG 2.3 GTDI AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108676585
Cover Note Number	

Driver

Name of Driver	JOSEPH YEO PENG SIONG
NRIC No	S9616316I
Date Of Birth	23/04/1996
Occupation	INDOOR
Date Of Driving Pass	18/11/2016
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81831081
Fax Number	
Contact Number	OFFICE-81831081
Email Address	NOEMAIL

Address	89 YISHUN STREET 81 #11-10
Postcode	768449
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF9425T - Toyota Aygo
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/FIN No:


Accident Sketch Plan

SKETCH PLAN

Vehicle A: SMK 3416 C

Vehicle B: GB+9425T

LAUREL CHURCH



CHINA STREET X SOUTH CANAL RD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date & time, I, vehicle 'A', SMK 3416 C
 was travelling straight along the stated venue suddenly, the
 rear right door of vehicle 'B', GB+9425T, hit onto my
 vehicle's left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	144H
Vehicle Details	
Vehicle No.:	SMK3416C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	FORD
Vehicle Model:	MUSTANG 2.3 GTDI AT
Primary Colour:	Orange
Manufacturing Year:	2016
Engine No.:	G5300984
Chassis No.:	1FA6P8TH9G5300984
Maximum Power Output:	233.2 kW (312 bhp)
Open Market Value:	\$42,536.00
Original Registration Date:	22 Sep 2016
First Registration Date:	22 Sep 2016
Transfer Count:	①
Actual ARF Paid:	\$51,551.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2026
PARF Rebate Amount:	\$38,663.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$38,310.00
Total Rebate Amount:	\$76,973.00

The information contained herein is correct as at 10 Dec 2019

OK



Mustang 2.3A EcoBoost

Price Range ▾

Depreciation ▾

2016 ▾

Vehicle Type ▾



Home » Used Cars » Orchard Credit Pte Ltd » Ford Mustang 2.3A EcoBoost

Ford Mustang 2.3A EcoBoost

Overview

Financial

Insurance

Accessories

Similar

Research

Photos


Map

PREM




ORCHARD CREDIT | PRE-OWNED CARS

Price	\$162,800		
Depreciation ⓘ	\$19,980 /yr View models with similar depre	Reg Date	13-Oct-2016 (6yrs 10mths 2days COE left)
Mileage	43,000 km (13.6k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	\$1,520 /yr	Transmission	Auto
Dereg Value ⓘ	\$75,325 as of today (change)	OMV ⓘ	\$42,906
COE ⓘ	\$53,001	ARF ⓘ	\$52,069
Engine Cap	2,261 cc	Power	233.2 kW (312 bhp)
Curb Weight ⓘ	1,692 kg	No. of Owners ⓘ	1
Type of Vehicle	Sports Car		



Price Chart



Click on the point to view the vehicle

Features

Powered By 2.3L EcoBoost 4 Cyl Engine, Torque 432 Nm, 5.5s (0 To 100 Km/H), 6 Speed Automatic Transmission, 314hp. View specs of the Ford Mustang (2016)

Accessories

Roush-Hood Scoop, Cervini Side Scoop, Upper & Lower Front Grille, Lower Lip Spoiler, Vossen Rims, Shaker Pro Premium Audio System, Keyless Entry.

Description

1 Owner, 2 Digit License Plate, Full Agent(Regent Motors) Servicing Records, Brilliant Competition Orange With Black Interior, Warranty To Oct 2021, Lovingly Kept By Owner, Come By To Our Showroom Or Call Our Sales Consultants For An Appointment To View This Amazing Muscle Vehicle, Another Pristine Preowned Vehicle From Orchard Credit.

Category

PARF Car, Premium Ad Car

Status

Available

Resource

Compare

Free

00A = 4/12/19

MV - 154000

PV - 76973

NV - 77000

Mileage → 6 yrs 9 mths

Age → 19000

19000 ÷ 12 = 1583

= 114000 + 14247

+ 25775

= 154022

Shortlist

Compare

Add no

Report Error

More Actions

Seller Information

Orchard Credit Pte Ltd

17 vehicles for sale, 7 sold in past 3 mths

📍 1 Chang Charn Road #01-02

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2019		06 Dec 2019 10:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JONG FRESH SUPPLIES PTE LTD , Co. Reg. No.: 200107204H		
Main Claimant:	ONG LAY TIN , ID: S6802144H		
Vehicle Reg. No.:	SMK3416C	Date of Loss:	04/12/2019 11:00 - :59 [38 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 613559	Policy/Cover Note No.:	29075429MKC (Comprehensive) Coverage: 10/04/2019 - 09/04/2020
Vehicle Reg. No. (Insured):	GBF9425T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 07/12/2019]		
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Elin Cai @ 9450 7920.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS























[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK3416C (613559)**
[GBF9425T]
TP
ONG LAY TIN
Dec 4 2019 11:00AM
[JONG FRESH SUPPLIES PTE LTD]
Zoom Autowerks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/12/19 12:11	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	09/12/19 12:12	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
4	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
5	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
6	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
7	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
8	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
9	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
10	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
11	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
12	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
13	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
14	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
15	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
16	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
17	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
18	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
19	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
20	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
21	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
22	09/12/19 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
23	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
24	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
25	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
26	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
27	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
28	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
29	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
30	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
31	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
32	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
33	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
34	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>
35	09/12/19 12:13	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	09/12/19 12:13	General View	 Load JPG	☑
37	09/12/19 12:13	General View	 Load JPG	☑
38	09/12/19 12:13	General View	 Load JPG	☑
39	09/12/19 12:13	General View	 Load JPG	☑
40	09/12/19 12:13	General View	 Load JPG	☑
41	09/12/19 12:13	General View	 Load JPG	☑
42	09/12/19 12:13	General View	 Load JPG	☑
43	09/12/19 12:13	General View	 Load JPG	☑
44	21/01/20 10:28	After Repair Photo	 Load JPG	☑
45	21/01/20 10:28	After Repair Photo	 Load JPG	☑
46	21/01/20 10:28	After Repair Photo	 Load JPG	☑
47	21/01/20 10:28	After Repair Photo	 Load JPG	☑
48	21/01/20 10:28	After Repair Photo	 Load JPG	☑
49	21/01/20 10:28	After Repair Photo	 Load JPG	☑
50	21/01/20 10:28	After Repair Photo	 Load JPG	☑
51	21/01/20 10:28	After Repair Photo	 Load JPG	☑
52	21/01/20 10:28	After Repair Photo	 Load JPG	☑
53	21/01/20 10:28	After Repair Photo	 Load JPG	☑
54	21/01/20 10:28	After Repair Photo	 Load JPG	☑
Documentation			1 per page ▼	☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/12/19 15:20	TPD SMK3416C - ACCIDENT REPORT	 Load PDF	
2	05/12/19 15:20	TPD SMK3416C - PRI	 Load PDF	
3	06/12/19 09:31	Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19021551/HQF3S2
Date: 24/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29075429MKC
Claimant Vehicle No: SMK3416C Insured Vehicle No: GBF9425T
Date of Loss: 04/12/2019 Nature of Claim: TP Claim No: 613559

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK3416C
Make & Model: FORD MUSTANG, 2.3 (A) Engine No: G5300984
Reg. Date: 22/09/2016 (Man. Year: 2016) Chassis No: 1FA6P8TH9G5300984
Colour: Grey Odometer: 28097 km
Engine Capacity: 2261 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40ZR19 Rear Tyre Size: 255/40 R19
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/12/2019
Date Inspected: 06/12/2019 Inspected At: Blk 15 Kaki Bukit Road 4 #01-53
Estimated Period of Repair: 3.0 days Repairer: Zoom Autowerks Pte Ltd

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2020)
Parts:	M1-COUPE	FORD MUSTANG 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3416C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >