

LKR Like AIG
COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.07.2020

Time: 11:48:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305411760
REGN NO : SH 7720S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 18.10.2018
DATE/TIME IN : 18.07.2020 08:05
ACCIDENT DATE : 17.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1 L	430.90	20.00	344.72	del
0002	04-01-0104-0633-G	IONIQV1-3 MOULDING-FRONT	1 L	93.60	20.00	74.88	X
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	del
0004	04-01-0104-2971-G	IONIQVC BRACKET-FR BUMPER	1 L	35.00	20.00	28.00	?
0005	04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1 L	28.00	20.00	22.40	?
0006	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1 L	588.80	20.00	471.04	del
0007	04-01-0104-2934-G	IONIQVC GUARD ASSY-FRONT	1 L	114.70	20.00	91.76	?
0008	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1 L	26.60	20.00	21.28	del
0009	03-01-0104-2061-G	IONIQV1&3 CAP ASSY-WHEEL	1 L	346.40	20.00	277.12	del
0010	28-01-0103-0003-A	(I40)FRT DOOR LOGO CTPL	1 N	75.00	2.00-	75.00	del

SUB-TOTAL : 1,423.80

JOB NATURE

0000 L PANEL BEATING (repair frt door Rh)

700.00 480.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.07.2020

Time: 11:48:44

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305411760
REGN NO : SH 7720S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 18.10.2018
DATE/TIME IN : 18.07.2020 08:0
ACCIDENT DATE : 17.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0001 23-502	SPRAYPAINT ON AFFECTED AREA	650.00	600
0002 17-01	CHECK ALL LIGHTING	50.00	30.
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30.
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	80.00	✓

SUB-TOTAL : 1,530.00

TOTAL : 2,953.80

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanfer 97495749
"WP"
P/P history before paint
tanfer @ lkkauto.com.
20/7/20 @ 4pm
03 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

59 Loyang Drive Singapore 508969
 383 Sin Ming Drive Singapore 575717
 45 Pankaj Road Singapore 602288
 320 Tampines Road Singapore 520549

24 Sennok Loop Singapore 758156
 7 Sungei Kadut Way Singapore 718791
 501 Yishun Industrial Park A Singapore 768771

Member of COMFORTDELGRO

Date/Time: 18.07.2020 10:38

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.:305411760

COMFORT TRANSPORTATION PTE LTD
 7010045
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65508755

REGN NO:
SH 7720S

MILEAGE

MAKE:
HYUNDAI

FUEL

MODEL
IONIQ(G2)

DATE/TIME IN
18.07.2020 08:05

YR OF MANU.
18.10.2018

TARGET DATE

CHASSIS CODE
KMHC851CVKU114775

COMPLETION DATE/TIME:

ALG


JOB DESCRIPTION

Accident Date: 17.07.2020
 ATURE: 3P 17.07.2020

/NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 7720S

LKE

Vehicle No.:

SH 7720S

Service Advisor

Signature/Date

ed to Service Reception upon collection

Name of Service Advisor

Date

To be kept by Security Guard