

RERPORT-ID : TAC019R
 USER-ID : amoppr10

ACCIDENT REPORT

DATE : 13/07/2020 15:07:32
 Page : 1 of 2

Company	SBS	District	SE	IP NUMBER	
Duty IO	NORLELA A. YUSOFF	Report No.	E/2692/2020	Accident Date	13/07/2020
Report Date	13/07/2020	Shift Code	PM SHIFT	Accident Time	07:45
Place of Accident	Right turn into Dunearn Rd				
Road Name	Farrer Rd	Road Name Junction	Dunearn Rd		

Accident Type	TRAFFIC	Final Cause	
Weather Code	CLEAR	Nature Of Accident	MINOR
Operating Hours	WORKED 1 HR 30 MINS	Road Surface	DRY
Traffic Volume	HEAVY	Type Of Location	CONTROLLED X-JUNCTION
Traffic Control	UNCONTROLLED	Traffic Flow	ONE WAY
Collision With	VEHICLE	Ambulance Convey	N
Fatal	0	Type Of Collision	SIDE SWIPE - SAME DIRECTION
Police Report	N	Serious Injury	0
Bus Towed	N	Police Report Number	Photo Taken Y
Urgent CBR Status	N	Sketch	Y
Damage To Bus		CFMS Case	N
Facts of Incident	SBS6008R, right portion scratches		
Brief Particulars	NA		
Reason for Late Report			

STATEMENT READ OVER TO ME
 AND I AFFIRM IT TO BE TRUE AND CORRECT

SIGNATURE OF STAFF

CHANG SU PING
 Admin Personnel
 Ang Mo Kio Depot

NAME AND DESIGNATION OF RECORDER

RERPORT-ID : TAC019R

USER-ID : amoppr10

ACCIDENT REPORT

DATE : 13/07/2020 15:07:32

Page : 2 of 2

Buses Involved in the Accident

1 Bus No : SBS6008R Bus Model : MB Citaro O530, SD, AC, 2 Axle Bus Park : BRBP CCTV : Y

Driver Involved in the Accident

1 Driver Category :	BC	Driver No :	78791	Svc No :	186
Gender :	FEMALE	Name :	Goh Siam Kheng	Svc RG :	TPI
SAP RG:	TPRG	NRIC :	**850B	Lic Class :	
Date Join :	03/10/2016	Nationality :	Singaporean	Lic Exp Date :	31/12/2999
LSvc :	3.77	Age :	70	Postal Code :	541117
Address :	Blk 117A Rivervale Dr	#03-78			

Third Party Details

1 Name :	Puar Hai Kiat	Race :	CHINESE	Vehicle No :	SCR7509S
NRIC :	**	Age :	0	Veh Color :	
Gender:		Contact No :	9735 6247	Veh Type :	
Veh Damage :	Left front damaged			Veh Make :	

Witness Details