PRS Filed By: GQ | REF: CS3/MSG20007523/Gtf3

PRS

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / [TP] / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s ASSURE AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S [✓] |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBB 5074U Yr Regn: 20 May/2009

Type: M.Car / M.Cycle / Bus / Van / [Lorry] / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA DYNA 150 c.c 2982

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 330743 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFAT35Y10K200506

Gen. Cond: [Good] / Fair / Poor / Burnt

Steering: [Inorder] / Jammed / Leaked / Burnt or

Brake: [Inorder] / Jammed / Leaked / Burnt or

Modi : [Nil] / S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: 155R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / [YOKO] or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 5 mm | R/Bal. | 5 mm |
| L/Bal. | 5 mm | L/Bal. | 5 mm |
| D.O.A. | | D.O.I. | 28-07-2020 |

Survey held at W/S 12pm

Des. of Damages : Frt / Rear / [O/S] / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | $1000 - $2000 |

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($ )

[ ] : Interview ($ )

[ ] : Tech. Invs ($ )

[ ] : Weekend ($ )

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL