

ASS. REC. BY: Paul

REF:

cc4/FCI20007533/Rlea3

3792

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 3662Jat Workshop m/s WAH HONGof 36, TOH HUAN RD BAY #01-36Insured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 66K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 3662J Yr Regn: 2017 / MARType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VOLKSWAGEN GOLF 1.4 TSI c.c. 1395Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 50016 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZH W098999Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt or _____Brake: Order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/01/2020

Survey held at

WAH HONG

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 21/07/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.F. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

379Z

Vehicle No.:

SLM3662J

Vehicle to be Exported:

No

Intended Deregistration Date:

31 Jul 2020

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

GOLF 1.4 TSI AT 5G13HZ

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

CZC153701

Chassis No.:

WWWZZZAUZHW098999

Maximum Power Output:

92.0 kW (123 bhp)

Open Market Value:

\$20,488.00

Original Registration Date:

28 Mar 2017

First Registration Date:

28 Mar 2017

Transfer Count:

0

Actual ARF Paid:

\$10,684.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Mar 2027

PARF Rebate Amount:

\$8,013.00

Intended COE Rebate Details

COE Expiry Date:

27 Mar 2027

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$51,000.00

COE Rebate Amount:

\$32,900.00

Total Rebate Amount:

\$40,913.00

The information contained herein is correct as at 14 Jul 2020

OK

Used 2017 Volkswagen Golf 1.4A

Merimen e-Claims

PARF/COE R

mart.com/used_cars/info.php?ID=912590&DL=1000

► Volkswagen Golf 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$68,800

Depreciation ⓘ \$9,150 /yr
View models with similar depre

Reg Date 28-Jun-2017
(6yrs 11mths 6days COE left)

Mileage 67,000 km (21.9k /yr)

Manufactured ⓘ 2016

Road Tax ⓘ \$624 /yr

Transmission Auto

Dereg Value ⓘ \$37,667 as of today (change)

OMV ⓘ \$20,453

COE ⓘ \$42,801

ARF ⓘ \$10,635

Engine Cap 1,395 cc

Power 92.0 kW (123 bhp)

Curb Weight ⓘ 1,249 kg

No. of Owners ⓘ 2

Type of Vehicle Hatchback

Features

1.4L 7 Speed TSI Turbocharged Engine, Multi Function Steering Wheel, Electric Brake Hold, Electric Parking Brake, View specs of the Volkswagen Golf (2012)

Accessories

Bluetooth, Carplay, All Round Front And Back Sensors, Reverse Camera, Front Dash Cam, Auto Retractable Side Mirrors With Indicator Lights, Fog Lamps.