ASS. REC. BY: Adrian Liny	
ASSI	IGNMENT 1968
From: Date:	Veh No: ST 9743 A Yr Regn: 1282 1 Jun
estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Volkswager Beltle. c.c 1285.
at Workshop m/s	Colour While A/C: Insured / Std / NI / NA
,	Sp.Reading /464 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: 118334419 *
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modir: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 155/60 R/S
(Policy Condition)	R: 185/60845
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Neren.
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent?: Yes or No	R/Balmm R/Balmm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 10/24/15
Lum Sum: % 3 Val.: Yes or No	Survey held at Reuse
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
79 ALG.	
•,	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
	: Interview (\$) Photos
Report Format :	:Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$)	:Weekend (\$)
	TOTAL