

ASS. REC. BY:

REF:

CS/CTI 20007637/R143

6354

CORRECTION: 2029/143

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TPTWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 2050Aat Workshop m/s Wah Hongof 38, TOH Guan RO Bays #01-57Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 42K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJN 2050AYr Regn: 2009 / FEBType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA COROLLA ALTIS 1.6 A c.c 1598Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 233490

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53 ZEG 106128718Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 14/01/2020D.O.I. 28/07/2020Survey held at Wah HongDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SJN2050A TOYOTA COROLLA ALTIS 1.6A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Front bumper <i>de /</i>		350.00	
1	Front reinforcement ?		280.00	
1	Front sponge ?		120.00	
1	Front grille <i>cm /</i>		250.00	
1	Front TOYOTA emblem <i>new /</i>		75.00	
1	Front lower grille <i>2 de /</i>		120.00	
1	Bonnet <i>repair</i>		550.00	
1	Bonnet hinge LH X		35.00	
1	Bonnet hinge RH X		35.00	
1	Headlamp RH X		300.00	
1	Headlamp LH X		300.00	
1	Support panel <i>repair</i>		480.00	
		Less 25%	2895.00	
			723.75	
			2171.25	
	<u>SPECIAL NETT ITEMS</u>			
1	Front bumper clips <i>new /</i>		35.00	
1	Front grille clips <i>new /</i>		25.00	
1	Front license plate with holder <i>cm /</i>		45.00 <i>35</i>	
	Total Parts		2276.25	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. **SJN2050A TOYOTA COROLLA ALTIS 1.6A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1000.00	3000 400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400 500
3	To remove and re-fit wiring and check all electrical components	120.00	X
4	To provide anti-rust treatment on affected area	100.00	X
Labour Total :		2020.00	
TOTAL (PARTS & LABOUR):		4296.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010568

4 days

4/5

28/07/2020 @ 1425

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/07/2020 11:43
Date Of Accident	14/01/2020 09:15
Exact Location Of Accident	MALAYSIA TUAS CHECKPOINT
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN2050A
Insured/Policyholder	
Name Of Registered Owner	TAN SIANG PING
NRIC No	SXXXX635H
Email Address	SPTAN_MY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98511587
Alternative Phone No	OFFICE-98511587

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00002391
Cover Note Number	

Driver

Name of Driver	TAN SIANG PING
NRIC No	SXXXX635H
Date Of Birth	02/10/1977
Occupation	INDOOR
Date Of Driving Pass	07/07/2001
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98511587
Fax Number	
Contact Number	OFFICE-98511587
Email Address	SPTAN_MY@HOTMAIL.COM

Address APT BLK 659A JURONG WEST STREET 65 #06-323
Postcode 641659
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name ANYANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 2 JURONG WEST AVENUE 5, POSTCODE: 649482, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-7929999 - FAX NO: 67912972
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT NO. J/20200705/2026 FOR ACCIDENT DETAILS.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SMD4289H
Vehicle Make/Model/Colour TOYOTA COROLLA ALTIS BLACK
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver NG
NRIC/Passport Number
Contact Number 88182254
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passengers

Sketch Plan Pg. 1


SKETCH PLAN

MALAYSIA TIRAS
CHECKPOINT

'B' Car Hit 'A' Car

B: SMD 4289H

A: SJN 2050A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report no. J/202000705/2026.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 6/7/2020

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 6/7/2020

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



J/20200705/2026

1 of 2

POLICE REPORT (NP299)

Report No. J/20200705/2026

Police Station Of Origin
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Date/Time Report Made 05/07/2020 13:07	Vide Report No.	Station Diary No. 38
Name Of Informant TAN SIANG PING	Address APT BLK 659A JURONG WEST STREET 65 #06-323 SINGAPORE 641659	
ID Type / ID No. NRIC NO / S7774635H	Contact No. Home/Office Mobile 98511587	
Nationality MALAYSIAN	Email Address	
Occupation Regional manager	Sex Male	Age 42
Institution/School Name	Date of Birth 02/10/1977	Race Chinese
Date/Time Of Incident 14/01/2020 09:00 - 14/01/2020 10:00	Location Of Incident Malaysia Custom Checkpoint MALAYSIA	

Brief details.

On 14/01/2020 at around 0900hrs to 1000hrs, I was driving my vehicle, SJN2050A from at the Tuas Checkpoint heading towards the Malaysia Checkpoint. Just as I reached the Malaysia Checkpoint at the Checking bay, there was another vehicle, SMD4289H in front of my vehicle and was swerving left to right as I assumed that the driver did not knew where to go. The vehicle then proceed to make a right turn and suddenly make a stop as the driver drove into the wrong direction. The vehicle then reversed quickly and went straight to the Checking Point. I then followed the vehicle from behind. When the driver reached the


Signature Of Officer Recording The Report:

J / Sgt 2 MOHAMMAD ISKANDAR ZULHAQIM BIN ZULKENAIN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp NUR AIN BINTE ABDUL WAHID
Contact No.: 9632 9150

Authentication Stamp



Signature Of Informant:

Date/Time:
05/07/2020 13:07

Classification Of Case:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



J/20200705/2026

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20200705/2026

Checking Bay, he alighted from his vehicle for the Custom Officer to make a check on his vehicle. Upon alighting, the driver did not realise that his vehicle's gear was put on reverse instead of neutral and thus the vehicle reverse and hit my vehicle's front part. My vehicle's front part, bumper, bonnet & etc. were damaged from the impact of the traffic accident. I am not injured. I do not have any in car camera in my vehicle.

I wish to state that the driver of SMD4289H and I have agreed to settle the matter privately and that he promise to pay for my vehicle's damages but as time goes by, he had been avoiding me to call me back to settle my vehicle's damages. I also wished to state that the driver of SMD4289H admitted that the traffic accident was his fault. I also wished to state the traffic accident was witnessed by the Malaysian Custom Officer who was checking on the said driver's vehicle at that time. I am lodging this report for record purposes and claiming of insurance.


Signature Of Officer Recording The Report:

J / Sgt 2 MOHAMMAD ISKANDAR ZULHAQQIM BIN
ZULKENAIN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp NUR AIN BINTE ABDUL WAHID
Contact No.:

Authentication Stamp



Signature Of Informant:

Date/Time:
05/07/2020 13:07

Classification Of Case:

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

Singapore NRIC

635H

SJN2050A

No

31 Jul 2020

TOYOTA

COROLLA ALTIS 1.6 AUTO

Silver

2008

3ZZ4829406

MR053ZEE106128718

80.0 kW (107 bhp)

\$16,084.00

07 Feb 2009

07 Feb 2009

1

\$16,084.00

Forfeited

-

\$0.00

06 Feb 2029

A - Car (1600cc & below)

10

\$25,727.00

\$21,913.00

\$21,913.00

The information contained herein is correct as at 07 Jul 2020

OK

Used 2009 Toyota Corolla Altis 1.6

Merimen e-Claims

Enquire Vehicle Tra

armart.com/used_cars/info.php?ID=908247&DL=1000

Toyota Corolla Altis 1.6A (COE till 03/2029)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$43,000

Depreciation \$4,960 /yr

Reg Date 31-Mar-2009
(8yrs 8mths 2days COE left)

Mileage 165,000 km (14.6k /yr)

Manufactured 2009

Road Tax \$816 /yr

Transmission Auto

Dereg Value \$22,147 as of today (change)

OMV \$16,990

COE \$25,525

ARF \$16,990

Engine Cap 1,598 cc

Power 80.0 kW (107 bhp)

Curb Weight 1,195 kg

No. of Owners 2

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Toyota Corolla Altis (2008-2013)

Category

COE Car, Direct Owner Sale

Status

Av