

ASS. REC. BY:

REF:

CC4/111 2000 7665/ pa3

0790

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMT 5325Xat Workshop m/s KAH MOTORof 255 ALEXANDRA RDInsured: 111

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 68k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMT 5325X Yr Regn: JUNE 2020Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 2022 1.3 CVT c.c. 1318Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 000781 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JHMAK 3850LS 2179.53

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO ☒ YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/07/2020D.O.I. 03/08/2020Survey held at KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

» Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	079D
Vehicle No.:	SMT5325X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Aug 2020
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	L13B15000731
Chassis No.:	JHMGK3850L5217953
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,678.00
Original Registration Date:	26 Jun 2020
First Registration Date:	26 Jun 2020
Transfer Count:	0
Actual ARF Paid:	\$6,678.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2030
PARF Rebate Amount:	\$5,008.00

COE Expiry Date:	25 Jun 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,699.00
COE Rebate Amount:	\$32,353.00
Total Rebate Amount:	\$37,361.00

The information contained herein is correct as at 03 Aug 2020

OK

Silver

Used 2020 Honda Jazz 1.3A for

Merimen e-Claims

Enquire Vehicle Tr

mart.com/used_cars/info.php?ID=899876&DL=1000

Honda Jazz 1.3A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$66,248

Depreciation  \$6,670 /yr
View models with similar depre

Reg Date 20-Jan-2020
(9yrs 5mths 16days COE left)

Mileage 4,500 km

Manufactured  2019

Road Tax  \$578 /yr

Transmission Auto

Dereg Value  \$35,750 as of today (change)

OMV  \$16,145

COE  \$32,889

ARF  \$6,145

Engine Cap 1,318 cc

Power 73.0 kW (97 bhp)

Curb Weight  1,052 kg

No. of Owners  1

Type of Vehicle Mid-Sized Sedan

Features

Digital Dash Board, Rear Sensors And Reverse Cameras. Front Camera. Solar Films (Reduce Heat From Sun) On Windows. View specs of the Honda Jazz (2014-2017)

Accessories

One Year Free Road Tax And Free Servicing Around 3 Years, Warranty 3 Years From KAH Motors

Reason For Considering To Sell Is Due To Covid 19. Loss Of Income. I Found A Job So I Can