



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Third Party

Ins Company : _____

Excess : _____

Date of Accident : _____

Suggested Days of Repair : _____

Vehicle No. : FBL1477P

Make & Model : YAMAHA MT-09 ABS

Year of Manufacture : 2016

Chassis No. : JYARN29S000004022

Engine No. : N701E062426

Policy No. : _____

Time of Accident : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Repair Estimates

Parts (a) Cost / List Price Items	<u>\$-</u>
Plus/Less	<u>\$-</u>
Total of Cost / List	<u>\$-</u>
(b) Nett Price Items	<u>\$-</u>
Less	_____
Total of Nett Item	_____
(c) Special Nett Items	<u>\$2,500.00</u>
Total Parts Cost (Appendix A)	<u>\$2,500.00</u>
Labour (Appendix B)	<u>\$150.00</u>
Total Repair Cost	<u>\$2,650.00</u>

Contact No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : ~~RASUL~~ - RASUL - Hp 90010068

Company : LKK AUTO CONSULTANT P/L

Survey conducted on : 28/07/2020 at 1410

Remarks By Surveyor : email: rasul@lkkauto.com

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 1 day(s)

(c) Resurvey : Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 28/07/2020

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 320 UBI ROAD 3 SINGAPORE 408649
 TEL :68438723/68438736 Fax:67436072

Parts

Vehicle No : FBL1477P Case Owner : 0
 Make & Model : YAMAHA MT-09 ABS Year Manufacture : 2016
 Chassis No : JYARN29S000004022 Engine No : N701E062426
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : Third Party

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	SIREN ASSY <i>vis /</i>	1				\$1,600.00	
2	FRONT CRASH BAR - LEFT <i>slr /</i>	1				\$425.00	
3	FRONT CRASH BAR - RIGHT <i>x</i>	1				\$425.00	
4	TOWING FROM ACCIDENT SCENE <i>/</i>	1				\$50.00	
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

