

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2020 16:09
Date Of Accident	25/07/2020 14:10
Exact Location Of Accident	IKEA TAMPINES CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS184U
Insured/Policyholder	
Name Of Registered Owner	CALDRON TAN HENG KIAT
NRIC No	SXXXX557B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91790046
Alternative Phone No	OFFICE-91790046

Vehicle Particulars

Manufacturer	AUDI
Model	A5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	GA452837/1
Cover Note Number	

Driver

Name of Driver	CALDRON TAN HENG KIAT
NRIC No	SXXXX557B
Date Of Birth	03/12/1992
Occupation	INDOOR
Date Of Driving Pass	14/11/2018
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91790046
Fax Number	
Contact Number	OFFICE-91790046
EMail Address	NOEMAIL

Address BLK 111 SERANGOON NORTH AVE 1 #06-611
Postcode 550111
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : UNKNWON
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: WITH OWNER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SML7319T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver YEAP SHIUH HUI BENNY (YE XUHUI)
NRIC/Passport Number SXXXX056I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



vehicle A: 365124U
 vehicle B: 5ML7319T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25th July at about 2:19pm, I was driving at IKEA Tempe's carpark heading straight when a vehicle ~~hit~~ ^{laned} me on the left. As we proceeded to exchange particulars and he informed me to get an quotation from my workshop for the repairs needed for my car. His carplate number is 5ML7319T.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name
 NRIC/EPN No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	557B
Vehicle Details	
Vehicle No.:	SGS184U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Aug 2020
Vehicle Make:	AUDI
Vehicle Model:	A5 SPORTBACK 2.0 TFSI QU
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CDN203976
Chassis No.:	WAUZZZ8T2BA088656
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$47,558.00
Original Registration Date:	28 Jul 2011
First Registration Date:	28 Jul 2011
Transfer Count:	3
Actual ARF Paid:	\$47,558.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2021
PARF Rebate Amount:	\$23,779.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$6,642.00
Total Rebate Amount:	\$30,421.00

The information contained herein is correct as at 03 Aug 2020

OK

Condition Codes
 (1) Item (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Bent (8) Sealed (9) Stuffed (10) Buckled (11) Abrasion (12) Missing (13) Necessary (14) Missing
 (15) None (16) Unconformal (17) Not Working

MOTOR CAR (LH)

ACTION (AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Conforming (NC)

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector	CR4	I	
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish Inner	CR4	I	
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor	BT	I	
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock	Jam	I	
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1000	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket	R		
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991468	Frt Bumper Sponge			
1010	991427	Frt Bumper Protector			
1011	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1020	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	CR4	I	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector	CR4	I	
		Frt inner shield	CR4	I	

Vehicle No: 565 184U

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector	CR4	I	
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1000	992958	Rear Bumper			
1007	992976	Rear Bumper Bracket			
1008	993068	Rear Bumper Side Retainer			
1009	993045	Rear Bumper Reinforcement			
1010	993077	Rear Bumper Sponge			
1011	993040	Rear Bumper Protector			
1015	993026	Rear Bumper Moulding			
1017	993023	Rear Bumper Lower Spoiler			
1018	993851	Rear LH Taillamp			
1020	993436	Rear LH Fender			
1021	993449	Rear LH Fender Protector	CR4	I	
1022	990247	Sticker			
		Frt Left wheel bearing	Jam	I	
		Frt LH Tyre	Cut	I	
		Rear LH Tyre	Cut	I	
		Frt LH Wheel Rim	Cut	I	
		Rear LH Wheel Rim	Cut	I	

No of Items: 13

Assessor: Sun An