

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.07.2020

Time: 13:47:01

Page: 1

LKK-

Ag Asia-CL(S)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305413177  
REGN NO : SHC3383P  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 19.11.2015  
DATE/TIME IN : 27.07.2020 09:50  
ACCIDENT DATE : 25.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G WING MIRROR RH

1 670.00 20.00 536.00

SUB-TOTAL : 536.00

JOB NATURE

0000 PB PANEL BEATING

150.00

0001 SP SPRAYPAINT CHARGE

150.00

0002 17-01 CHECK ALL LIGHTING

30.00

SUB-TOTAL : 330.00

TOTAL : 866.00

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE:

Tanjiu 97495749  
27/7/20 @ 4pm  
01 day  
c/s Resey after repair  
Tanjiu @ 11:00am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: