

LKK-
COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.07.2020

Time: 13:47:01

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010945
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
55508755

Job Asia-CLF5
IS

JOB NO : 305413177
REGN NO : SHC3383P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 19.11.2015
DATE/TIME IN : 27.07.2020 09:50
ACCIDENT DATE : 25.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G WING MIRROR RH

1 670.00 20.00 536.00

SUB-TOTAL : 536.00

JOB NATURE

0000 PB PANEL BEATING

150.00

0001 SP SPRAYPAINT CHARGE

150.00

0002 17-01 CHECK ALL LIGHTING

30.00

SUB-TOTAL : 330.00

TOTAL : 866.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE:

Tan Jia 97495749
27/7/20 @ 4pm
01 day
c/s Resurvey after repair
Tan Jia C. Khawson

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579 011
Mainline : 65 6383 6280 Facsimile : 65 6280 9755

Workshops

591 Lavang Drive Singapore 508969 24 Serangoon Road Singapore 258158
383 Sin Ming Drive Singapore 575717 7 Serangoon Road Singapore 258191
45 Poyiad Road Singapore 609786 501 Nanyang Industrial Park A Singapore 108132
320 Telok Ayer Street Singapore 054154

Date/Time: 27.07.2020 12:39

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO: 305413177

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO

SHC3383P

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE TIME IN 27.07.2020 09:50

YR OF MANU.

19.11.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMGU080554


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 25.07.2020

NATURE: 3P 25.07.2020

W/NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Edge of Slip

Exit Pass

No. SHC3383P

LIMITS

Vehicle No.:

SHC3383P

Service Advisor

Signature/Date

Name of Service Advisor