

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3350D

MAKE :

MODEL I-40

DATE 05/15/20 12:00 AM

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
1	FRONT LH FENDER			\$663.00
1	FRONT BUMPER SIDE BRACKET LH			\$24.60
1	HEAD LAMP LH			\$1,388.00
1	LH WHEEL HUB COVER			\$107.10
	SUB TOTAL			\$3,234.90
	20.00%			\$646.98
	DISCOUNTED TOTAL			\$2,587.92
	Labour Charge			
	Panel Beating			\$450.00
	Spray Painting Charge			\$500.00
	Check lighting			\$60.00
	tuff kote			\$60.00
	TOTAL LABOUR			\$1,070.00
	ESTIMATE TOTAL			\$3,657.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanjin 97495449

'up'

28/7/20 @ 3pm

2 days

4/3 Resing after repair
 tanjin e. l. hant. w.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Lorong Road Singapore 609649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728741
501 Yishun Industrial Park A Singapore 768731

Date/Time: 27.07.2020 16:25

Page : 1

A member of COMFORTDELGRO

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305413428

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

(R)
(P)

COUNT CARD NO.

REGN NO.: SHD3350D

MAKE: HYUNDAI

MODEL I-40

YR OF MANU. 21.07.2016

CHASSIS CODE KMHLB41UMGU092192

MILEAGE

FUEL

E.....1/2.....F

DATE/TIME IN 27.07.2020 13:05

TARGET DATE


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.07.2020

NATURE: 3P 27.072020

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD3350D CHIANG

Vehicle No.: SHD3350D

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard