



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	SOM02Q77
Reference	None 
Loss Date	1 July 2020
Report Date	3 Jul 2020 12:00:00 AM
Request Date	9 July 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Own Damage Investigation

Actions

Next Step

Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident Vehicle SML6658X
Registration #

Make JEEP

Model WRANGLER UNLIMITED
SAHARA

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

WEE HONG BEE VICTOR
BLK 506 BEDOK NORTH AVENUE 3, #08-325,
460506, Singapore
98572222
VICTOR_WEE@JUNNIMED.COM

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions

OD-INCONSISTENT DAMAGE INVESTIGATION

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	
 ASM_LKKInvoice_AC2005635.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	18 August 2020
 Investigation Report.pdf	Reports & Statement	Investigator / Adjustor Report	LKK AUTO CONSULTANTS PTE LTD (OD)	18 August 2020
 INSURED FURNISHED SCENE PHOTO.pdf	Evidence	Photos	HO Winnie	9 July 2020
 SML6658X.pdf	Evidence	Photos	Sam Chan (AXA)	8 July 2020
 SML6658X.pdf	Evidence	Photos	Sam Chan (AXA)	7 July 2020



SMIL6658X INSD GIA REPORT.PDF

Reports &
TYPE
Statement

GIA Report
SUB-TYPE

K. H. E. Nagesh
AUTHOR

DATE
6 July 2020
UPLOADED