

<<

Service Request Details

Claim

S0M02Q77

Reference

None 

Loss Date

July 1, 2020

Report Date

Jul 3, 2020 12:00:00 AM

Request Date

July 9, 2020

Due Date

July 16, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Own Damage Investigation

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SML6658X

Model
WRANGLER UNLIMITED SAHARA

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

WEE HONG BEE VICTOR
BLK 506 BEDOK NORTH AVENUE 3, #08-325, 460506, Singapore
98572222
VICTOR_WEE@JUNNIMED.COM

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions
OD-INCONSISTENT DAMAGE INVESTIGATION

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME

Accident Statement

TYPE

Reports & Statement

SUB-TYPE

AUTHOR

Merimen

DATE UPLOADED

NAME

INSURED FURNISHED SCENE PHOTO.pdf

TYPE

Evidence

SUB-TYPE

DATE UPLOADED July 9, 2020

NAME  [SML6658X.pdf](#)

TYPE Evidence

SUB-TYPE Photos

AUTHOR Sam Chan (AXA)

DATE UPLOADED July 8, 2020

NAME  [SML6658X.pdf](#)

TYPE Evidence

SUB-TYPE Photos

AUTHOR Sam Chan (AXA)

DATE UPLOADED July 7, 2020

NAME  [SML6658X INSD GIA REPORT.PDF](#)

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR KALE Nagesh

DATE UPLOADED July 6, 2020
