

ASS. REQ. BY:

Steve

REF:

C53/A1620097752/Estf3

ASSIGNMENT

From:

PRS

Date:

Estimated Cost:

OD / TP / NYS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 9555H

Yr Regn:

27/7/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SUZUKI Swift

c.c

1586

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Rending

166436

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSAE2C 1150551947

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SRim / STD A/Rim or

Tyre Size:

F:

195/5R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/7/20

D.O.I.

28/7/20

Survey held at

Sin Seng Hong Spray

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-60K

Date/Time, File Pass to?

20/07/2020

1) TYPIST

Date/Time, File Return to?

2)

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

\$ + RS, \$

Phone

Others

TOTAL

Rep. Form:

PRS

Lump Sum / L.E.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the CUA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if requested.

ACCIDENT STATEMENT

Date Of Report 24/07/2020 14:50
Date Of Accident 24/07/2020 12:00
Exact Location Of Accident KPE ECP AFTER TAMPINES ROAD EXIT
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMR9555H
Insured/Policyholder
Name Of Registered Owner ELYN YAP
NRIC No S7430400A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90911221
Alternative Phone No OFFICE-90911221
Vehicle Particulars
Manufacturer SUZUKI
Model SWIFT
Exact Purpose for which vehicle was being used at time of accident LEISURE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5118257458
Cover Note Number DRIVO CLASSIC
Driver
Name of Driver ELYN YAP
NRIC No S7430400A
Date Of Birth 12/02/1974
Occupation INDOOR
Date Of Driving Pass 05/01/2010
Driving Experience 10 YEARS AND 6 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-90911221
Fax Number
Contact Number OFFICE-90911221
Email Address NOEMAIL

BLK 624C #15-324
PUNGGOL CENTRAL
823624

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 5

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name MACPHERSON NEIGHBOURHOOD POLICE POST

Police Station Address ROAD: BLK 54 PIPIT ROAD #01-82/84, POSTCODE: 370054, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-7449999 - FAX NO: 65476366

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Refer to sketch plan

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGE5533L

Vehicle Make/Model/Colour SUBARU XV

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SER AH BOK

NRIC/Passport Number S1634951H

Contact Number 92957715

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLX2008Y

Vehicle Make/Model/Colour

BMW

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMED TAHIR

NRIC/Passport Number

S1564303Z

Contact Number

98486895

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SFP1919M

Vehicle Make/Model/Colour

LEXUS GS250

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

WONG H Y

NRIC/Passport Number

S1297139G

Contact Number

97309630

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

FBF6704H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

MALE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

RIDER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBF6704H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report No. 511

DOA 21.07.2020
Time 12.00 hrs

Report Date & Start Time 21.07.2020 14.42
Vehicle No. S41R9885JL Reporting Type

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

24.07.20 / 14.42

Policyholder's Signature / Date & Time

24.07.20 / 14.42

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel


**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
MacPherson North
54 Phipps Road #02-84 SINGAPORE
370054
Tel No. 1800-7449999



1/20200724/0122

1 of 3

Report No. 1/20200724/0122

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/07/2020 16:12	Vide Report No.: F/20200724/0122	Station Diary No.: 17
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: ELYN YAP			Address: APT BLK 624C PUNGGOL CENTRAL #15-324 SINGAPORE 823624	
ID Type / ID No.: NRIC NO / S743 1400A			Contact No.: Home/Office: Mobile: 90911221	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 46	Date of Birth: 12/02/1974	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: SALES			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/07/2020 12:00	Type of Location: Straight Road
Location: Along Road 1 TAMPINES ROAD				
KPE (MCE) AFT TAMPINES RD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGE5523L	Car	SUBARU		Silver	Seriously Damaged	0
SMR9555H	Car	SUZUKI	SWIFT 1.3 AT	Black	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMR9555H	NTUC Income Insurance Co-Operative Limited	5118257458	23/07/2020	26/07/2021



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
MacPherson NPP
54 Pict Road #01-82/84 SINGAPORE
370054
Tel No 1800-7449999



T/20200724/2071

2 of 3

Report No T/20200724/2071

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved No			
No. of Pedestrians Injured NIL		Use of Pedestrian Crossing NA	
Driver			
Name ELYN YAP		ID No	S7430400A
Related Vehicle	NIL	Contact No.	90911221
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Person Involved			
Name SER AH BOK		ID No.	S1634951H
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 24/07/2020 @ 1200hrs, I was driving along KPE (MCE) after Tampines Road when there was a car which was in front of mine which made a sudden emergency brake. I then also made a brake to my vehicle as to slow down and avoid any collision with the car in front of mine. When I did a brake on my car, another driver (SGE5533L) whom was from the rear of my vehicle did not managed to stop his car on time and then cause his vehicle to hit the rear of my car.

My car suffered damaged on the rear such as dents on the rear bumper, top right of the plate number and also the area on top of where the plate number of my car is. I also realized that there was a chain collision consisting of 4 cars and 1 motorcycle when I got off my vehicle to see what happened

I am lodging this report because I was instructed by the Traffic Police as the motorist whom was riding the motorcycle (FBF 6703H) got injured and was conveyed by the ambulance. I am also lodging this report as instructed by my insurance company for insurance purposes



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
MacPherson NPP
54 Phipp Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7441999



1120200724/2071

3 of 3

Report No. T120200724/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 MUHAMMAD FAEZ BIN ROSLI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt NOOR HIDAYAH BIN IE
ABDULLAH
Contact No: 65476251
Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

Signature Of Informant:

Date/Time:
24/07/2020 16:12

Classification Of Case:

SIGNATURE

11) Denied (12) Denied (13) Denied (14) Cracked (15) Cracked (16) Scratched
 17) Performed (18) Shifted (19) Buckled (20) Broken (21) Necessary
 22) Missing (23) Torn (24) Unconfirmed (25) Not Working

MOTORCAR (Rear)

ACTION (AC)
 (1) Replace (✓) (2) Repair (R) (3) Check (C)
 (4) Not Consistent (NC)

Aug 2005

Vehicle No:

SMR 955SH

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate	✓		
1138	993627	Rear Number Plate Base	✓		
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	✓		
1149	993045	Rear Bumper Reinforcement	✓		
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	✓		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	✓		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	✓		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

4 repair days