

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jul 2020		28 Jul 2020 10:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Yu Kwok Wai , ID: S2220677Z, GST No.: NA, Tel: +6597373213, Email: freddyyu@singnet.com.sg									
Main Claimant: YUEN MEI YEE , ID: S7244834J									
Vehicle Reg. No.:	SDR360T	Date of Loss:	24/07/2020 08:00 - :59 [3 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 246054	Policy/Cover Note No.:	1001094107 (Comprehensive) Coverage: 17/09/2019 - 16/09/2020						
Vehicle Reg. No. (Insured):	SGC7291G	Policy No. (Claimant):	2070052240						
		Excess:							
Repairer:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2, 569535 Ang Mo Kio - Tel: 6481 7773								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 29/07/2020]								
Driver/Custodian (Insured):	BAY LEE HOON (/ Female) , NRIC: S1170181G, Tel: +6596699827 Email:								
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants - Kenneth Kong. Contact: Calvin @ 6481 7773								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDR360T (246054)**
[SGC7291G]
TP
YUEN MEI YEE
Jul 24 2020 8:00AM
[Yu Kwok Wai]
Tropical Success Auto Care

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:41	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:47	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	24/07/20 13:44	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/08/20 09:29	General View	Load JPG	☒
2	04/08/20 09:29	General View	Load JPG	☒
3	04/08/20 09:29	General View	Load JPG	☒
4	04/08/20 09:29	General View	Load JPG	☒
5	04/08/20 09:29	General View	Load JPG	☒
6	04/08/20 09:29	General View	Load JPG	☒
7	04/08/20 09:29	General View	Load JPG	☒
8	04/08/20 09:29	General View	Load JPG	☒
9	04/08/20 09:29	General View	Load JPG	☒
10	04/08/20 09:29	General View	Load JPG	☒
11	04/08/20 09:29	General View	Load JPG	☒
12	04/08/20 09:29	General View	Load JPG	☒
13	04/08/20 09:29	General View	Load JPG	☒
14	04/08/20 09:29	General View	Load JPG	☒
15	04/08/20 09:30	General View	Load JPG	☒
16	04/08/20 09:30	Odometer Reading	Load JPG	☒
17	04/08/20 09:30	Chassis Number	Load JPG	☒
18	05/08/20 11:56	Dismantled Parts	Load JPG	☒
19	05/08/20 11:56	Dismantled Parts	Load JPG	☒

Video			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
20	05/08/20 11:56	Dismantled Parts	Load JPG	☒
21	05/08/20 11:56	Dismantled Parts	Load JPG	☒
22	05/08/20 11:56	Dismantled Parts	Load JPG	☒
23	05/08/20 11:56	Dismantled Parts	Load JPG	☒
24	05/08/20 11:56	Dismantled Parts	Load JPG	☒
25	05/08/20 11:56	Dismantled Parts	Load JPG	☒
26	05/08/20 11:56	Dismantled Parts	Load JPG	☒
27	05/08/20 11:56	Dismantled Parts	Load JPG	☒
28	05/08/20 11:56	Dismantled Parts	Load JPG	☒
29	05/08/20 11:56	Dismantled Parts	Load JPG	☒
30	05/08/20 11:56	Dismantled Parts	Load JPG	☒
31	05/08/20 11:56	Dismantled Parts	Load JPG	☒
32	05/08/20 11:56	Dismantled Parts	Load JPG	☒
33	05/08/20 11:56	Dismantled Parts	Load JPG	☒
34	05/08/20 11:56	Dismantled Parts	Load JPG	☒
35	05/08/20 11:56	Dismantled Parts	Load JPG	☒
36	05/08/20 11:56	Dismantled Parts	Load JPG	☒
37	05/08/20 11:56	Dismantled Parts	Load JPG	☒
38	05/08/20 11:56	Dismantled Parts	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:43	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/07/20 13:53	PRI EMAIL	Load PDF	
2	27/07/20 13:54	E-FILE SGC7291G (oi)	Load PDF	
3	28/07/20 10:01	Agree on SJE	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	28/07/20 10:26	Email - Outsource Instruction	Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:41	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:47	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/07/20 13:44	Accident Photo	Load JPG	☒
2	24/07/20 13:44	Accident Photo	Load JPG	☒
3	24/07/20 13:44	Accident Photo	Load JPG	☒
4	24/07/20 13:44	Accident Photo	Load JPG	☒
5	24/07/20 13:44	Accident Photo	Load JPG	☒
6	24/07/20 13:44	Accident Photo	Load JPG	☒
7	24/07/20 13:44	Accident Photo	Load JPG	☒
8	24/07/20 13:44	Accident Photo	Load JPG	☒
9	24/07/20 13:44	Accident Photo	Load JPG	☒
10	24/07/20 13:44	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print

Video			1 per page ▾	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail Print
1	24/07/20 13:43	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20007753/GTF3S2**Date:** 19/08/2020REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001094107
Claimant Vehicle No :	SDR360T	Insured Vehicle No :	SGC7291G
Date of Loss:	24/07/2020	Nature of Claim:	TP
		Claim No:	246054

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR360T		
Make & Model:	MERCEDES-BENZ A200, 1.3 SALOON PROGRESSIVE (R18 LED) (A)	Engine No:	28291480182620
Reg. Date:	01/04/2020 (Man. Year: 2019)	Chassis No:	WDD1770872J108563
Colour:	Red	Odometer:	2850 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/07/2020	
Date Inspected:	03/08/2020 Inspected At:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2 Singapore 569535
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Aug 2020)		
Parts:	144	MERCEDES-BENZ A200 1.3 SALOON PROGRESSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SDR360T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >